



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20327
Pack Slip:5945

Service Date: Nov 17, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer:	8030030	City:	OAKVILLE	Received:	Nov 08, 2023
Name:	ZANCOR THE BRANCH CONDOS	Service Phone(s):		Time:	1ST CALL
Service Fax:		Site Phone:	(416) 566-2066	Order:	H801167-1
Site Fax:		Lot#:	6TH FLOOR	Phase:	605

RESIDENT INFORMATION

Home Owner Name:	DILOVAR KADIROVA	Address:	
Home Phone(s):		Work Phone(s):	
Cell Phone(s):	647-345-7389, 647-891-1768	Email(s):	DILOVARKADIROVA1@GMAIL.COM, KH.KHAKIMOV@GMAIL.COM

LINKED ORDER INFORMATION (H801167-1)

Customer:	8030030 ZANCOR THE BRANCH CONDOS	House Model:	6TH FLOOR
Lot #:	6TH FLOOR	Phase:	Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #164435 & 164465 - PDI - LIVING ROOM - WINDOWS - MULIN SHORT UPPER RIGHT OF SLIDING DOOR

DAI #164466 - PDI - BEDROOM 2 - WINDOWS - MULIN SHORT AT LEFT SIDE OPERATING WINDOW

DAI #164467 - PDI - MASTER BEDROOM - WINDOWS - MULIN SHORT AT FIXED WINDOW. TOP AND BOTTOM

DAI #164468 - PDI - MASTER BEDROOM - WINDOWS - SCRATCHED SCREEN AT WINDOW AND MULIN LEFT SIDE

DAI #166732 - INTERVAL - OTHER - GENERAL - FILLING CORNERS IN WINDOWS

DAI #166733 - INTERVAL - MAIN BATHROOM - GENERAL - FILL BEHIND TOILET

Problem Description: Complete

☐ Warranty

Material \$ _____

Labour \$ _____

☐ CHARGEABLES

Material \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

KHEM