

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076 WO # W20443 Pack Slip:5968

Service Date: Nov 15, 2023

\$ 500 C 10 C C C C C C C C C C C C C C C C						•	
Priority:	Normal		Status:			25686455000000000000000000000000000000000	
BUILDE	R		Otatus.	SCHEDULED			
Customer	r: 8030030		City:		~~~~		
Name:	ZANCOR THE BRANCH	H CONDOS	Service Phone(s):	OAKVILLE	Received:	Nov 14, 2023	
Service F	ax:		Site Phone:		Time:		
Site Fax:			Lot#:	(416) 566-2066	Order:	H801168-1	
RESIDE	NT INFORMATION		LOUT.	7TH FLOOR	Phase:	716	
Home Ow	ner Name:	4.00	Address:				
Home Phone(s):							
Cell Phone(s):			Work Phone(s): Email(s):				
LINKED	ORDER INFORMATION (I	H801168-1)	Linaii(s):				
Customer:	8030030 ZANCOR THE B	RANCH CONDOS					
Lot #:	7TH FLOOR	Phase:	,		FLOOR		
SERVICE	INSTRUCTIONS			Elevation:	****		
	ATE AND CORRECT						
UNIT 716 -	THE BACK OF THE FIXED S	SLIDING DOOR IS	COMING APART I	ETTING COLD AID IN			
		1		-LITING COLD AIR IN			
Problem De	escription: <u>Camplete</u>						
Warranty	······································						
Material \$				CHARGEABLES			
Labour \$			Material \$				
σα, φ			Labour \$		•		
Cause:			P.O.#:				

Solution:							

D							
Date Comp	pleted:		. Approv	ed:			
				ed:			
	Time:		Service Signatu	ire:			
			- · g. · a.u		HEM		