



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20008

Pack Slip:5968

Service Date: Nov 15, 2023

Priority: Normal Status: SCHEDULED

**BUILDER**

Customer: 8030030 City: OAKVILLE Received: Oct 20, 2023  
Name: ZANCOR THE BRANCH CONDOS Service Phone(s): Time:  
Service Fax: Site Phone: (416) 566-2066 Order: H801168-1  
Site Fax: Lot#: 7TH FLOOR Phase: 707

**RESIDENT INFORMATION**

Home Owner Name: JESSICA GARABETIAN Address:  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 647-964-2226 Email(s): JESSVAHEGARA@GMAIL.COM

**LINKED ORDER INFORMATION (H801168-1)**

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 7TH FLOOR  
Lot #: 7TH FLOOR Phase: Elevation:

**SERVICE INSTRUCTIONS**

\*\*\*CLOSING ON NOVEMBER 8TH 2023\*\*\*

INVESTIGATE AND CORRECT

DAI #165496 - MASTER BEDROOM - WINDOWS - TRIM CRACKED AND DIRTY

**PARTS REQUIRED**

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE GLASS STOPS PROFILE #59 2PCS @ 90" LONG IN WHITE	TBA	OTHER - REPLACEMENT PARTS	90	BONE WHITE UC113812	2

Problem Description: Complete

☐ Warranty

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

☐ CHARGEABLES

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

P.O.#: \_\_\_\_\_

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: \_\_\_\_\_

Approved: \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

KHEM