



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W19360

Pack Slip:5567

Service Date: Oct 02, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Sep 19, 2023
Name: ZANCOR THE BRANCH CONDOS Service Phone(s): Time:
Service Fax: Site Phone: (416) 566-2066 Order: H801164-1
Site Fax: Lot#: 3RD FLOOR Phase: 322

RESIDENT INFORMATION

Home Owner Name: Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): Email(s):

LINKED ORDER INFORMATION (H801164-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 3RD FLOOR
Lot #: 3RD FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

CLOSING ON OCTOBER 25TH 2023

INVESTIGATE AND CORRECT

DAI# 163056 - PDI - MASTER BEDROOM - WINDOWS - CRACK MULLIN AT UPPER RIGHT SIDE ABOVE OPERATING WINDOW

DAI# 163059 - PDI - LIVING ROOM - FLOORING - DENT ON MULLIN AT SLIDING DOOR AND RIGHT SIDE - DONE

PLEASE TAKE PICTURES OF DAMAGE

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

KHEM