Enrollment:

Purchaser Name: Nikita Mehra

Phone Res:

Phone Bus: (416) 704-3632

Closing Date: November 30, 2023 Inspector: Alexandria Damianidis HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 83B / 1B

Plan:

Address: 32 Gatherwood Terrace

Municiaplity:

Inspection Date: November 24, 2023

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

LAUNDRY ROOM			
CABINETS	GABLES NOT INSTALLED THROUGHOUT		
WINDOWS	WINDOW CRANK NOT INSTALLED THROUGHOUT		
EXTERIOR			
NOTE:	POWER WASH REQUIRED - REMOVE MORTAR FROM WINDOWS		
GARAGE DOORS	ADJUST WEATHERSTRIP AT LEFT GARAGE DOOR		
FOYER/HALL			
STAIRS	HOLE AT FIRST LANDING AT STAIRS TO 2ND FLOOR		
	REMOVE STAIN FROM PICKETS THROUGHOUT		
	HOMEOWNER UNHAPPY WITH STAIN COLOUR, OFF FROM HARDWOOD AND DIFFERENT		
	COLOURS THROUGHOUT STAIRS, INSPECT		
	TRIM PIECE TO BE CUT AND FILL GAP		
ELECTRICAL/LIGHTING	CONFIRM WHAT 2ND SWITCH IS FOR -NOT TURNING ANYTHING ON		
KITCHEN			
CABINETS	CHIPS AT FILLER PIECE ABOVE SINK		
	PAINT FEELING AT HOOD FAN VENT AND FILLER PIECE PEELING BOTH SIDES		
	AS PER HO, HOOD FAN SHOULD BE TOUCHING CEILING, HO ADVISED THIS IS BEING FIXED NOV		
	28		
ELECTRICAL/LIGHTING	HIDE VALANCE WIRES, VISIBLE		
WINDOWS	SLIDING DOOR TRIM BOWED RIGHT SIDE		
COUNTERTOPS	REMOVE GLUE MARKS FROM COUNTERTOP AT WHOLE ISLAND		
MASTER ENSUITE BATH		•	
FLOORING	HEAT REGISTER NOT FITTING BY TOILET		
MASTER BEDROOM			
ELECTRICAL/LIGHTING	PLATE MISSING		
NOTE:	TOUCH UP DOOR JAMBS AND BASEBOARDS THROUGHOUT - CRACKS		

Enrollment:

Purchaser Name: Nikita Mehra

ZANCOR HOMES PDI

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: 83B / 1B

Plan:

Address: 32 Gatherwood Terrace

. . .

Municiaplity:
Inspection Date: November 24, 2023

Phone Res:
Phone Bus: (416) 704-3632
Closing Date: November 30, 2023
Inspector: Alexandria Damianidis

SHARED ENSUITE VANITY CABINETS AS PER HO WRONG HANDLES INSTALLED - SHOULD BE GOLD AND NOT BLACK WALLS TOUCH UP DOOR LOCKS THROUGHOUT HOME, CAN SEE UNPAINTED WOOD AND WINDOW COUNTERTOPS SCRATCHES ON COUNTERTOP MULTIPLE AREAS TUB REDO SILICONE AT BATH - DIRT TRAPPED BELOW BEDROOM #3 WALK IN CLOSET AS PER HO WALK IN CLOSET SHOULD NOT HAVE SHELVING, ASKED TO HAVE THIS REMOVED LIVING ROOM ELECTRICAL/LIGHTING AS PER HO WOOD INSERTS MISSING POWDER ROOM NOTE: REMOVE BLACK PAINT FROM COUNTER TOP AND IN KITCHEN

A REFERENCE FOR FUTURE WAR	RANTY REQUESTS. o designate someone to conduct the PDI in th	E HOME'S CONDITION BEFORE THE PURCHASS neir place should ensure they provide written auth	
I have inspected my new home and	I agree that the description of the items listed	on this form are accurate.	
Nikita Mahua	-6/60		
Nikita Mehra			
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature
		Alexandria Damianidis	AD
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature
Date (YYYY/MM/DD)	2023/11/24	November 24, 2023	