



**NEWMAR WINDOW MFG. INC.**  
**ALPA LUMBER GROUP**

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2  
TEL (905) 672-1233 FAX (905) 672-1076

**WO # W20756**

**Pack Slip:5698**

**Service Date: Dec 01, 2023**

Priority: Normal Status: **SCHEDULED**

**BUILDER**

|              |                          |                   |                |           |              |
|--------------|--------------------------|-------------------|----------------|-----------|--------------|
| Customer:    | 8030030                  | City:             | OAKVILLE       | Received: | Nov 30, 2023 |
| Name:        | ZANCOR THE BRANCH CONDOS | Service Phone(s): |                | Time:     |              |
| Service Fax: |                          | Site Phone:       | (416) 566-2066 | Order:    | H801165-1    |
| Site Fax:    |                          | Lot#:             | 4TH FLOOR      | Phase:    | 432          |

**RESIDENT INFORMATION**

|                  |                |
|------------------|----------------|
| Home Owner Name: | Address:       |
| Home Phone(s):   | Work Phone(s): |
| Cell Phone(s):   | Email(s):      |

**LINKED ORDER INFORMATION (H801165-1)**

|           |                                  |              |            |
|-----------|----------------------------------|--------------|------------|
| Customer: | 8030030 ZANCOR THE BRANCH CONDOS | House Model: | 4TH FLOOR  |
| Lot #:    | 4TH FLOOR                        | Phase:       | Elevation: |

**SERVICE INSTRUCTIONS**

INVESTIGATE AND CORRECT

DAI #168363 - PDI - LIVING ROOM - WINDOWS - ADJUST SLIDING DOOR

DAI #168384 - PDI - BEDROOM #2 - WINDOWS - WINDOW SCREEN NOT INSTALLED

Problem Description: Complete

☐ Warranty

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

☐ CHARGEABLES

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

P.O.#:

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: \_\_\_\_\_

Approved: \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

KHEM