



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W20877
Pack Slip:5698

Service Date: Dec 08, 2023

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Dec 06, 2023
Name: ZANCOR THE BRANCH CONDOS Service Phone(s): Time:
Service Fax: Site Phone: (416) 566-2066 Order: H801165-1
Site Fax: Lot#: 4TH FLOOR Phase: 450

RESIDENT INFORMATION

Home Owner Name: MARILIA SUZANA GAMBOA Address:
Home Phone(s): Work Phone(s):
Cell Phone(s): 416-999-1492 Email(s): MARI42GG@GMAIL.COM

LINKED ORDER INFORMATION (H801165-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 4TH FLOOR
Lot #: 4TH FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #168924 - PDI - MASTER BEDROOM - CHIP ON MULIN TRIM AT UPPER FIXED WINDOW LEFT SIDE AND WINDOW HANDLE AT OPERATING WINDOW

DAI #168927 - PDI - LIVING ROOM - INSPECT CRACKED MULIN TOP RIGHT CORNER OF SLIDING DOOR

DAI #168928 - PDI - LIVING ROOM - ADJUST SLIDING DOOR NOT LOCKING

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

BENNY