Enrollment:

Purchaser Name: ??????

Muhammad Hayat Chaudhary

Phone Res:

**Phone Bus:** (416) 836-0814 **Closing Date:** December 20, 2023

ZANCOR HOMES Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 155 Unit 3 / 1

Plan:

Address: 53 Minnock Street

Municiaplity:

Inspector: Alexandria Damianidis Page 1 of 2 Inspection Date: December 18, 2023

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be

selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH		
MIRROR	MIRRORS THROUGHOUT NOT INSTALLED.	 
NOTE:	UPGRADE BATHROOM ACCESSORIES NOT INSTALLED SEE PHOTOS	 
MASTER BEDROOM		
NOTE:	DAMAGED ASTRICAL AT HINGE	 
MAIN BATHROOM		
VANITY CABINETS	DAMAGED GABLE LEFT OFF SINK AT FLOOR LINE	 
BEDROOM #2		
FLOORING	OVERCUT AT CARPET AT ENTRANCE RIGHT SIDE.	 
BEDROOM #3		
FLOORING	BUDGE IN CARPET RIGHT OF WINDOW.	 
FOYER/HALL		
STAIRS	MISSING TRIM BELOW STRINGER AT STAIRS TO 3RED FLOOR	 
	TRIM AT STRINGER AT STAIRS TO 3RD FLOOR TRIMMED OUTSIDE OF STRINGER.	 
	OVERCUT OUTSIDE STRINGER BY 2ND STRINGER BELOW NOSING AT LANDING TO 3RD FLOOR	 
	STAIN REQUIRED AT TRIM BELOW NOSING AT MAIN FLOOR	 
	DENT ON 5TH TREAD AT STAIRS FORM LANDING TOO 2ND FLOOR.	 
	MISSING TRIM BELOW STRINGER AT LANDING TO MAIN FLOOR FROM 1ST FLOOR AND 1ST	
	FLOOR	
	DAMAGE NOSING AT FRONT FOYER.	 
KITCHEN		
CABINETS	DAMAGED AT INSIDE GABLE AT HINGE AT UPPER CABINET ABOVE FRIDGE.	 
	DAMAGED DW GABLE AT FLOOR LINE. LEFT SIDE.	 
	INSTALL KICKPLATE BELOW PANTRY	 
FLOORING	MISSING GROUT RIGHT OF SLIDING DOOR	 

Enrollment: Purchaser Name: ??????

Muhammad Hayat Chaudhary

Phone Res:

Phone Bus: (416) 836-0814 Closing Date: December 20, 2023 Inspector: Alexandria Damianidis



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 155 Unit 3 / 1

Plan:

Address: 53 Minnock Street

Municiaplity:

Inspection Date: December 18, 2023

POWDER ROOM		
NOTE:	CHIPPED KICKPLATE BELOW SINK	<del></del>
EXTERIOR		
NOTE:	GAP AT SOFFIT AND BRICK ABOVE FRONT PORCH.	

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. \* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. ?????? Muhammad Hayat Chaudhary Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature

Designate's Name (print) Designate's Signature Alexandria Damianidis Inspector's Name (print)

Inspector's Signature

2023/12/18 Date (YYYY/MM/DD) December 18, 2023