Enrollment:

Purchaser Name: Bharat KUMARI

Shweta KUMARI

Phone Res: (416) 887-2485 Phone Bus: (416) 887-2485

Closing Date: January 11, 2024 Inspector: Alexandria Damianidis HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 833 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 833

Municiaplity:

Inspection Date: January 10, 2024

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

## DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

## **OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MAGTER ENGLUTE BATH		
MASTER ENSUITE BATH		
MIRROR	MIRRORS THROUGHOUT NOT INSTALLED.	 
SHOWER ENCLOSURE	NOT INSTALLED.	 
VANITY CABINETS	GABLE SHORT RIGHT SIDE AT FLOOR LINE.	 
ELECTRICAL/LIGHTING	POT LIGHT NOT INSTALLED.	 
MASTER BEDROOM		
NOTE:	MISSING LIGHT FIXTURE INSIDE MASTER WALK IN CLOSET.	 
MAIN BATHROOM		
SHOWER ENCLOSURE	SHOWER GLASS NOT INSTALLED.	 
VANITY CABINETS	INSIDE GABLE BELOW SINK PEELING	 
ELECTRICAL/LIGHTING	POT LIGHT NOT INSTALLED.	 
KITCHEN		
CABINETS	CHIP AND VALANCE LEFT OF FRIDGE, CABLE AND ABOVE SINK AND LEFT OF STOVE.	 
	UPPER GABLE FILLER NOT SECURED, LEFT OF SINK	 
	SECURE FRIDGE, GABLE, AND KICKPLATE NOT FLUSH	 
SINK/FAUCET/PLUMBING	D/W NOT CONNECTED	 
COUNTERTOPS	SLAB BACKSPLASH LEFT OF STOVE AND BEHIND STOVE SHORT.	 
BEDROOM #2		
NOTE:	MIRROR, SLIDING DOORS NOT INSTALLED.	 
FOYER/HALL		
TRIM	LAUNDRY ROOM, DOOR TRIM RIGHT AND LEFT SIDE SHORT.	 

Enrollment:

Purchaser Name: Bharat KUMARI

Shweta KUMARI

Phone Res: (416) 887-2485
Phone Bus: (416) 887-2485
Closing Date: January 11, 2024
Inspector: Alexandria Damianidis

ZANCOR HOMES Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 833 / 1 Plan:

Address: 2450 Old Bronte Road, Suite 833

Municiaplity:
Page 2 of 2 Inspection Date: January 10, 2024

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Bharat KUMARI Shweta KUMARI Purchaser's Name (print) Purchaser's Name (print) Purchaser's Signature Purchaser's Signature Alexandria Damianidis Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature Date (YYYY/MM/DD) 2024/01/10 January 10, 2024