



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W21158  
Pack Slip:5945

Service Date: Jan 02, 2024

Priority: Normal Status: SCHEDULED

BUILDER

Customer: 8030030	City: OAKVILLE	Received: Dec 21, 2023
Name: ZANCOR THE BRANCH CONDOS	Service Phone(s):	Time:
Service Fax:	Site Phone: (416) 566-2066	Order: H801167-1
Site Fax:	Lot#: 6TH FLOOR	Phase: 625

RESIDENT INFORMATION

Home Owner Name:	Address:
Home Phone(s):	Work Phone(s):
Cell Phone(s):	Email(s):

LINKED ORDER INFORMATION (H801167-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS	House Model: 6TH FLOOR
Lot #: 6TH FLOOR	Phase: Elevation:

SERVICE INSTRUCTIONS

\*\*\*CLOSING ON JANUARY 12TH 2024\*\*\*

INVESTIGATE AND CORRECT

45" GLASS STOPS

DAI #170015 - PDI - MASTER BEDROOM - WINDOW MULLION CRACKED AT BOTTOM RIGHT CORNER OF FIXED WINDOW

Problem Description: Replaced Broken Glass Stops

<input type="checkbox"/> Warranty	<input type="checkbox"/> CHARGEABLES
Material \$ _____	Material \$ _____
Labour \$ _____	Labour \$ _____
	P.O.#: _____

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: \_\_\_\_\_ Approved: \_\_\_\_\_

Time: \_\_\_\_\_ Service Signature: \_\_\_\_\_ KHEM