Enrollment:

Purchaser Name: Ajay Jhajj

2286201 Ontario Inc

Phone Res:

Phone Bus: (416) 727-2009 Closing Date: January 29, 2024 HOMES

Page 1 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 176 - Unit 4 / 1B

Plan:

Address: 12370 Mclaughlin Road

Municiaplity:

Inspection Date: January 23, 2024

Inspector: Alexandria Damianidis

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

FOYER/HALL		
STAIRS	MISSING STAIN AT TREAD BELOW NOSING ABOVE RISER AT 2ND FLOOR	
	CHIP AT RAILING AT 1ST LANDING TO 3RD FLOOR	
	CHIP AT RIGHT RAILING AT STIARS FROM 2ND TO LANDING TO 3RD FLOOR BELOW NOSING.	
	CRACK AT INSIDE STRINGER BELOW NOSING AT STIARS FROM KITCHEN TO 1ST FLOOR.	
	STAIN ON 2ND TREAD FROM NOSING AT STAIRS FROM MAIN TOO 2ND FLOOR FROM 1ST.	
NOTE:	GLASS INSERT MISSING AT DEN	
	REPLACE JAMB AT LEFT ARCHYWAY AT ENTRANCE TO DEN LARGE GAP FILLED.	
FLOORING	INSPECT HUMP IN FLOOR FOR TOLERANCE LEFT SIDE OF WINDOW.	
	OVER CUT AT HRV VENT INSIDE DEN	
FRONT DOORS	DENT ON OPERATNG DOOR RIGHT SIDE	
	TRIM NOT SECURED BELOW GLASS @ FRONT DOOR.	
MASTER ENSUITE BATH		
NOTE:	OPERATING WINDOW NOT CLOSING.	
FAUCETS/PLUMBING	STANDARD BATH ACCESSORIES NOT INSTALLED.	
MASTER BEDROOM		
FLOORING	REMOVE STAIN OFF CARPET BELOW LIGHT	
	ADJUST OPERATING WINDOW LEFT OF DOOR	
MAIN BATHROOM		
COUNTERTOPS	CHIP AT LEFT EDGE	
NOTE:	OPERATING WINDOW NOT CLOSING	
GENERAL COMMENTS		
=	INSPECT DUCTS AT 3RD FLOOR NO AIR FLOW H.O REQUESTING TO INSPECT PRESSURE DROP	
	ACROSS THE COIL THAT CAN BE PLUGGED.	

Enrollment:

Purchaser Name: Ajay Jhajj

2286201 Ontario Inc

Phone Res:

Phone Bus: (416) 727-2009
Closing Date: January 29, 2024
Inspector: Alexandria Damianidis

ZANCOR HOMES

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 176 - Unit 4 / 1B

Plan:

Address: 12370 Mclaughlin Road

Municiaplity:

Inspection Date: January 23, 2024

1		
KITCHEN		
CABINETS	CHIP AT RIGHT FRIDGE PANEL AND REMOVE RED MARK	
	MISSING CORNER FILLER BELOW UPPER CABINETS	
	CHIP AT TOP GABLE AT SCREW HOLE AT UPPER LEFT CABINET LEFT OF STOVE.	
	DAMAGED BACK PANEL AT UPPPER CABINET LEFT OF STOVE 2ND FROM CORNER AND TOP	
	GABLE.	
FLOORING	CHIPPED TILE LEFT SIDE AT HEAT REGISTER BELOW SLIDING DOOR	
POWDER ROOM		
NOTE:	ADJUST OPERATING WINDOW INSIDE POWDER.	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Ajay Jhajj 2286201 Ontario Inc Purchaser's Signature Purchaser's Name (print) Purchaser's Name (print) Purchaser's Signature Alexandria Damianidis Designate's Name (print) Designate's Signature Inspector's Name (print) Inspector's Signature Date (YYYY/MM/DD) 2024/01/23 January 23, 2024