



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W21184

Pack Slip:5332

Service Date: Feb 07, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Dec 22, 2023
Name: ZANCOR THE BRANCH CONDOS Service Phone(s):
Service Fax: Site Phone: (416) 566-2066 Time:
Site Fax: Lot#: 8F-CRT Order: H801509-1
Phase: 836

RESIDENT INFORMATION

Home Owner Name: SIDDHARTH & KUSUM SHARMA Address: 836-2450 OLD BRONTE ROAD, OAKVILLE, ONTA
Home Phone(s): Work Phone(s):
Cell Phone(s): 647-966-3990, 416-887-6090 Email(s): SID27SHARMA@HOTMAIL.COM, D21SHARMA@HOTMAIL.COM

LINKED ORDER INFORMATION (H801509-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 8TH FLOOR COURTYARD
Lot #: 8F-CRT Phase: Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #170795 - PDI - LIVING ROOM - BALCONY SCREEN NOT INSTALLED - DONE

DAI #170804 - PDI - MASTER BEDROOM - WINDOW HANDLE NOT INSTALLED - DONE

SUPPLY AND INSTALL

UNIT 836 - MISSING PATIO SCREEN - SILVER HINGE LEFT - DONE

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
108	PURCHASED PATIO DOOR	WBCH8-WC	SCREENS	35 7/16 X 91	STEEL-CITY SILVER	1
2		N2		1/16	UCFX12200 LEFT	
Address Labels						
BCH-8F-1-29* - DONE						
109	REQUIRE WINDOW CRANK	MASTER	OTHER -	0 X 0	BONE WHITE UC113812	1
0		BEDROOM	REPLACEMENT PARTS			

Problem Description: Installed Patio Door Screen & Installed Crank Handle, Completed

☐ Warranty

☐ CHARGEABLES

Material \$

Material \$

Labour \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed: _____

Approved: _____

Time: _____

Service Signature: _____

STEEVEN