



**Zancor Homes (Wasaga River) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 08Jan24  
**Address:** 81 Sun Valley Avenue  
Wasaga, Ontario  
**Location:** Rivers Edge - Phase: 1 - Lot: 339  
**Today's Date:** 08Jan24  
**Contact(s):** Guiwen Chen - Home: (647) 526-9266 - (chch@live.ca)  
Wang Xiangrui  
**Email:** chch@live.ca

**Company:** Medi Group  
**Attention:**  
**Telephone:** (416) 741-2737  
**Fax:** (416) 741-1593

**Please Complete the following items:**

DAI	Type	Issue	Appt. Date/Time	Notes
170378	PDI	Exterior- General- right pier cap overcut		
170381	PDI	Exterior- General- inspect stone at sides of front door - not aligned		

**Date Completed:** \_\_\_\_\_

**Homeowner Signature:** \_\_\_\_\_

The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

**Date Completed:**  \_\_\_\_\_

**Trade &/or Service Tech.**

**Signature:** \_\_\_\_\_

**Print Name:** \_\_\_\_\_

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be**



# MEDI GROUP Service

WO Number : **W-091163**

WO Date : **29-Jan-2024**

Issued To : **MICHAEL KLOC**

**Builder :** Zancor **ZAN14**  
**Project :** ZANCOR-RIVERS EDGE-WASAG.6-22

**Lot No :** 339  
**Model :** 43-8 (A)

**Directions :** Wasaga Beach  
East side of Sunnisdale Road. North of  
Concession 12 Sunnisdale Road

**Address :**  
**Contact :**

**Main Brick :** Royal Gray

**Main Stone :**

**Accent Brick :**

**Accent Stone :**

INIT	Item	Work Description	PO	Builder Ref #
	1	1. RIGHT PIER CAP OVERCUT		339JAN824
	2	2. INSPECT STONE AT SIDES OF FRONT DOOR - NOT ALIGNED		S-070753
				339JAN824
				S-070753



\_\_\_\_\_  
**Homeowner Signature**

Jan 29  
**Date Completed**

\_\_\_\_\_  
**Site Super Signature**

\_\_\_\_\_  
**Date Completed**

**Special Notes :**

**COMPLETED FEB / 9 2024**