

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076 WO # W22202 Pack Slip:5919

Service Date: Feb 13, 2024

Priority:	Normal	Status:	SCHEDULED			
BUILDER		·				
Customer:	8030030	City:	OAKVILLE		Received:	Feb 08, 2024
Name:	ZANCOR THE BRANCH CONDOS	Service Phone(s):			Time:	7 00 00, 2024
Service Fax	x:	Site Phone:	(416) 566-206	6	Order:	H801166-1
Site Fax:		Lot#:	5TH FLOOR		Phase:	503
	TINFORMATION			***************************************		
	er Name: ARUN THOMAS ALEX	Address		***************************************		
Home Phon	• •	Work Ph	one(s):			
Cell Phone(	**************************************	Email(s):	ATHO	MASALEX@	@GMAIL.CC	M
	RDER INFORMATION (H801166-1)				**************************************	**************************************
Customer:		S	House Model:	5TH FLO	OR	
Lot #:	5TH FLOOR Phase:		Elevation:			
A SECURIO A ARRA AREA AREA AREA AREA AREA AREA A	INSTRUCTIONS TE AND CORRECT					
	AS PER ALYCIA (BUILDER) ALL OF THE ITE		TE, BUT THE SL	IDING DOC	OR STILL DO	DES NOT LOCK
UNIT 503 - A	4 4		TE, BUT THE SL	IDING DOC	OR STILL DO	DES NOT LOCK
UNIT 503 - A Problem Des  Warranty	6 19	s miss pl	TE, BUT THE SL	IDING DOO	OR STILL DO	DES NOT LOCK
UNIT 503 - A Problem Des Warranty Material \$	6 19	s miss pl	GEABLES	IDING DOO	OR STILL DO	DES NOT LOCK
UNIT 503 - A Problem Des  Warranty	6 19	CHAR	GEABLES	IDING DOC	OR STILL DO	DES NOT LOCK
UNIT 503 - A Problem Des Warranty Material \$ Labour \$	6 19	CHAR	GEABLES	IDING DOO	OR STILL DO	DES NOT LOCK
UNIT 503 - A Problem Des Warranty Material \$	6 19	CHAR Material \$	GEABLES	IDING DOO	OR STILL DO	DES NOT LOCK
UNIT 503 - A Problem Des Warranty Material \$ Labour \$	6 19	CHAR Material \$	GEABLES	IDING DOC	DR STILL DO	DES NOT LOCK
Problem Des Warranty Material \$ Labour \$ Cause:	scription: Lock who	CHAR Material \$ Labour \$ P.O.#:	GEABLES		DR STILL DO	DES NOT LOCA
Problem Des Warranty Material \$ Labour \$ Cause:	6 19	CHAR Material \$ Labour \$ P.O.#:	GEABLES	83		DES NOT LOCK