Enrollment:

Purchaser Name:

Chaundhry Mansoo Khalid

Phone Res:

Phone Bus: (647) 781-3366 Closing Date: February 22, 2024

HOMES

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 155 Unit 6 / 1

Plan:

Address: 47 Minnock Street

Municiaplity:

Inspection Date: February 16, 2024

Inspector: Gisella Fiore

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
CABINETS	CROWN MOULDING NOT FINISHED ABOVE FRIDGE.	
	CHIPPED BACK PANEL AT ISLAND FACING BREAKFAST AREA.	
	LEFT ISLAND GABLE FACING SLIDING DOOR BUBBLING AT FLOOR LINE	
	EXPOSED HOLES AT BACK PANEL INSIDE CABINET LEFT OF GARBAGE PULL OUT.	
	DENT ON LOWER LEFT CABINET BELOW SINK	
	REPLACE CABINET LOWER LEFT CORNER CABINET RIGHT AND LEFT CABINET DENTED	
	DENT ON LOWER RIGHT CABINET LEFT OF BANK OF DRAWER	
	RIGHT GABLE AT ISLAND FACING FRIDGE BUBBLING	
	HOOD FAN NOT INSTALLED CENTRED.	
	SCREW COVERED REQUIRED AT GABLE INSIDE FRIDGE LEFT SIDE	
	INSPECT SEAM ABOVE HOODFAN	
NOTE:	HOBBY GLASS INSERT NOT INSTALLED	
FOYER/HALL		
STAIRS	NOSING CUT IN TWO PIECE AT LANDING INFRONT OF POWER ROOM AT MAIN FLOOR AND	
	INSIDE STRINGER OVER CUT (LARGE GAP FILLED)	
	SEAM VIABLE AT STAIRS FROM MAIN TOO 2ND FLOOR	
	DENTS ON STRINGER AT STAIRS FROM MAIN TO 2ND FLOOR CEILING (X3)	
	CHIP AT INSIDE STRINGER AT LANDING TO 3RD FLOOR LEFT SIDE.	
FRONT DOORS	INSPECT OPERATING DOOR AT HINGE BOWED	
BEDROOM #4		
NOTE:	INSPECT FIXED WINDOW INSTALLED SLANTED AT CEILING AS PER HOMEOWNER SLANTED	
	LINE IN STIPPLE LEFT OF LIGHT.	

Enrollment: Purchaser Name: ??????

Chaundhry Mansoo Khalid

Phone Res:

Phone Bus: (647) 781-3366 Closing Date: February 22, 2024 Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Purchaser's Signature

Inspector's Signature

Lot / Phase: Block 155 Unit 6 / 1

Plan:

Address: 47 Minnock Street

Municiaplity:

Inspection Date: February 16, 2024

BEDROOM 4 ENSUITE		
VANITY CABINETS	CHIP AT KICKPLATE BY GABLE LEFT SIDE.	
	INSTALL TOLIET PAPER HOLDERS AS PER LOCATIONS	
BASEMENT		
NOTE:	HOMEOWNER REQUEST CEILING IN COLD ROOM INSPECTED AT CEILING DENTED.	
LIVING ROOM		
WALLS	INSPECT BUMP OUT WALL RIGHT OF POWDER ROOM AS PER H,O NO SQUARE TOUCH UP	
NOTE:	INSPECT FIXED WINDOW INSTALLED SLANTED AT CEILING AS PER HOMEOWNER SLANTED	
	INSPECT TOLERANCE.	
MASTER BEDROOM		
NOTE:	DAMAGED OPERATING DOOR BELOW HANDLE	
FLOORING	CARPET NOT GLUED RIGHT OF DOOR AT SEAM	
BEDROOM #2		
NOTE:	TRIM AT FIXED WINDOW NOT SECURED	
	RAISE CARPET BELOW WINDOW.	

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

??????

Purchaser's Name (print) Purchaser's Signature

Chaundhry Mansoo Khalid Purchaser's Name (print)

Gisella Fiore

Designate's Name (print) Designate's Signature

Inspector's Name (print)

Date (YYYY/MM/DD) 2024/02/16 February 16, 2024