



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W21798

Pack Slip:5332

Service Date: Feb 27, 2024

Priority: Normal Status: SCHEDULED

**BUILDER**

Customer: 8030030 City: OAKVILLE Received: Jan 23, 2024  
Name: ZANCOR THE BRANCH CONDOS Service Phone(s):  
Service Fax: Site Phone: (416) 566-2066 Time:  
Site Fax: Lot#: 8F-CRT Order: H801509-1  
Phase: 837

**RESIDENT INFORMATION**

Home Owner Name: RAHUL ARORA Address: 2450 OLD BRONTE ROAD, OAKVILLE, ONTARIO  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 905-599-6699 Email(s): MONICAS09@HOTMAIL.COM

**LINKED ORDER INFORMATION (H801509-1)**

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 8TH FLOOR COURTYARD  
Lot #: 8F-CRT Phase: Elevation:

**SERVICE INSTRUCTIONS**

\*\*\*ADDED ON FEB 12TH 2024\*\*\*

DAI #172722 - INTERVAL - LIVING ROOM - DAMAGE MULIN ABOVE SLIDING DOOR

INVESTIGATE AND CORRECT

UNIT 837 - BALCONY NOT LATCHING - COMP ON JAN 31ST

\*\*\*ADDED ON JAN 23RD\*\*\*

DAI #171720 & #171721 - PDI - BEDROOM 2 - DAMAGED MULIN TOP RIGHT CORNER OF FIXED WINDOW AND SECURE TRIM AT WINDOWS THROUGHOUT POLY SHOWING - COMP ON FEB 7TH 2024

DAI #171722 - PDI - BEDROOM 2 - MISSING SCREENS AT OPERATING WINDOW AND MULIN TOP RIGHT CORNER SHORT - COMP ON FEB 7TH 2024

**PARTS REQUIRED**

LN	Item Description	Location	Speciflcation	Size	Options	Qty
10	REQUIRE GLASS STOPS COMPLETED	TBA	OTHER - REPLACEMENT PARTS	120	BONE WHITE UC113812	4
113	NEWMAR ALUMINUM AWNING 3 COMPLETED	WBCH8-WC N7	SCREENS	27 7/8 X 18 3/4	BONE WHITE UC113812	1

**Address Labels**

BCH-8F-1-12

124	NEWMAR ALUMINUM AWNING 3	WBCH8-WC N18	SCREENS	20 X 18 3/4	BONE WHITE UC113812	1
-----	-----------------------------	-----------------	---------	-------------	---------------------	---

PO #91368 (SCREENCO MFG. L) ETA 02-22-2024 \*\* RECEIVED ON 02-23-2024

**Address Labels**

BCH-8F-1-21

Problem Description:

☐ Warranty

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

☐ CHARGEABLES

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

P.O.#: \_\_\_\_\_

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: \_\_\_\_\_

Approved:  \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: \_\_\_\_\_

MIGUEL