

## NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076 WO # W20584 Pack Slip:5567

BRAMPTON ON L6S 5P2 Service Date: Nov 24, 2023

Priority: Normal			Status:	SCHEDULED				
BUILDER			Otatus.	SCHEDULED		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	·	
Customer:	8030030		City:			···		
Name:	ZANCOR THE BRANCH	CONDOS	-	OAKVILLE		Received:	Nov 21, 2023	
Service Fax:		0011000	Service Phone(s): Site Phone:			Time:		
Site Fax:			Lot#:	(416) 566-2066		Order:	H801164-1	
*****************************	RESIDENT INFORMATION			3RD FLOOR	3RD FLOOR Phase: 349			
	Name: YUMEI ZHANG		· · · · · · · · · · · · · · · · · · ·		***************************************			
Home Phone(s):			Address:					
Cell Phone(s): 416-846-9923			Work Phone(s):  Email(s): XF040823@gmail.com, XF040823@gmail.com					
Children Color Col	DER INFORMATION (H	J201167 1\	Email(s):	XF040	)823@gma	il.com, XF04	0823@gmail.co	
	8030030 ZANCOR THE B	· · · · · · · · · · · · · · · · · · ·					y	
	3RD FLOOR		)	House Model:	3RD FLC	OR		
	STRUCTIONS	Phase:		Elevation:				
Access on a county of a consequency of the consequence	ON NOVEMBER 29TH 202	NA+++			***************************************			
	E AND CORRECT  PDI - BEDROOM #2 - WI	NDOWS - MISSIN	IG CRANK AT WIN	IDOW				
LN Item Descr	200200000000000000000000000000000000000							
10 REQUIRE WINDOW CRANK		Location	Specification	Size	•	Options		
IN WHITE COLOR		BEDROOM 2	OTHER - REPLACEMENT PARTS	DONE		WHITE UC1	13812	
Problem Descr	ription:			and the same and t				
Warranty								
Material \$		Sd	GEABLES					
Labour \$			Material \$					
			Labour \$					
Cause:			P.O.#:					
Solution:								
Date Comple	ted:		_ Appro	ved:				
Tiı	me:		_ Service Signat	ture:	KHE	i.M		