



NEWMAR WINDOW MFG. INC.  
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2  
TEL (905) 672-1233 FAX (905) 672-1076

WO # W19909

Pack Slip:5945

Service Date: Dec 07, 2023

Priority: Normal Status: SCHEDULED RELEASED

BUILDER

Customer: 8030030 City: OAKVILLE Received: Oct 17, 2023  
Name: ZANCOR THE BRANCH CONDOS Service Phone(s): Time:  
Service Fax: Site Phone: (416) 566-2066 Order: H801167-1  
Site Fax: Lot#: 6TH FLOOR Phase: 610

RESIDENT INFORMATION

Home Owner Name: SREEDHAR MUNDLURU & DIVYA DONT Address:  
Home Phone(s): Work Phone(s):  
Cell Phone(s): 416-885-0805, 416-989-1228 Email(s): SREE@SUNDINEPRODUCE.COM,  
DIVYA@SUNDINEPRODUCE.COM

LINKED ORDER INFORMATION (H801167-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS House Model: 6TH FLOOR  
Lot #: 6TH FLOOR Phase: Elevation:

SERVICE INSTRUCTIONS

\*\*\*CLOSING ON NOVEMBER 3RD 2023\*\*\*

6053698

INVESTIGATE AND CORRECT

DAI #164852 - PDI - BEDROOM 2 - WINDOWS - MULIN SHORT RIGHT AND LEFT SIDE OF WINDOW AND CRANK NOT INSTALLED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE L SHAPE @ 5/8" X 1" X @ 102 3/4" LONG IN WHITE	TBA	OTHER - REPLACEMENT PARTS	102 3/4	BONE WHITE UC113812 *SEE PICTURE ATTACHED*	1

Problem Description: 

☐ Warranty

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

☐ CHARGEABLES

Material \$ \_\_\_\_\_

Labour \$ \_\_\_\_\_

P.O.#: \_\_\_\_\_

Cause: \_\_\_\_\_

Solution: \_\_\_\_\_

Date Completed: 

Approved: \_\_\_\_\_

Time: \_\_\_\_\_

Service Signature: 

BENNY