Enrollment:

Purchaser Name: Baltej Singh Gill

Kiranjit Kaur Gill

Phone Res:

Phone Bus: (416) 358-8100

Closing Date: April 11, 2024 Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd. Lot / Phase: Block 176 - Unit 2 / 1B

Plan:

Address: 12366 Mclaughlin Road

Municiaplity:

Inspection Date: April 01, 2024

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

ADJUST BALCONY DOOR HARD TO LOCK		
ADJUST WINDOW NO CLOSING AND SCREEN TORN.		
DENT ON 7TH RISER AT STAIRS FROM MAIN TOO 3RD FLOOR		
HOLE ON RISER BELOW NOSING AT STAIRS FROM 2ND TO 1ST FLOOR		
CRACK ON 5TH TREAD AT STAIRS FROM 1ST TO 2ND FLOOR.		
FILLER BLOCK NOT INSTALLED LEFT OF FRIDGE.		
	ADJUST WINDOW NO CLOSING AND SCREEN TORN. DENT ON 7TH RISER AT STAIRS FROM MAIN TOO 3RD FLOOR HOLE ON RISER BELOW NOSING AT STAIRS FROM 2ND TO 1ST FLOOR CRACK ON 5TH TREAD AT STAIRS FROM 1ST TO 2ND FLOOR.	ADJUST WINDOW NO CLOSING AND SCREEN TORN. DENT ON 7TH RISER AT STAIRS FROM MAIN TOO 3RD FLOOR HOLE ON RISER BELOW NOSING AT STAIRS FROM 2ND TO 1ST FLOOR CRACK ON 5TH TREAD AT STAIRS FROM 1ST TO 2ND FLOOR.

Enrollment:

Purchaser Name: Baltej Singh Gill

Kiranjit Kaur Gill

Phone Res:

Phone Bus: (416) 358-8100
Closing Date: April 11, 2024
Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (Caledon) Ltd.

Lot / Phase: Block 176 - Unit 2 / 1B

Plan:

Address: 12366 Mclaughlin Road

Municiaplity:

Inspection Date: April 01, 2024

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.					
I have inspected my new home and I agree that the description of the items listed on this form are accurate.					
Baltej Singh Gill	Granist Gill	Kiranjit Kaur Gill			
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature		
		Gisella Fiore	HC		
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature		
Date (YYYY/MM/DD)	2024/04/01	April 01, 2024			