Enrollment:

Purchaser Name: Meenakshi Polepeddi

Phone Res: (647) 986-1502 Phone Bus: (437) 248-1977 Inspector: Gisella Fiore

Closing Date: November 02, 2023

HOMES

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 518 / 1 Plan:

Address: 2450 Old Bronte Road, Suite 518

Municiaplity:

Inspection Date: May 06, 2024

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER BEDROOM		
WALLS	OVER IT AT SPEAKER.	
KITCHEN		
CABINETS	ADJUST UPPER RIGHT CABINET RIGHT OF MICROWAVE.	
	CHIP AT 2ND BANK OF DRAWER AND BOTTOM RIGHT CABINET BELOW SINK 2) INSPECT UPPER	
	GABLE ABOVE SINK RIGHT SIDE FOR CHIP AT CROWN FILLER	
LIVING ROOM		
NOTE:	RATTLING NOISE OUT OF VENTING ABOVE HVAC DOOR.	

Enrollment:

Purchaser Name: Meenakshi Polepeddi

 Phone Res:
 (647) 986-1502

 Phone Bus:
 (437) 248-1977

 Closing Date:
 November 02, 2023

 Inspector:
 Gisella Fiore



Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 518 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 518

Municiaplity:

Inspection Date: May 06, 2024

Gisella Fiore Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.						
I have inspected my new home and I agree that the description of the items listed on this form are accurate.						
Meenakshi Polepeddi	Meneral					
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature			
Designate's Name (print)	Designate's Signature	Gisella Fiore Inspector's Name (print)	Inspector's Signature			
, ,		, ,	inspector's Signature			
Date (YYYY/MM/DD)	2024/05/06	May 06, 2024				