



Quality Sterling Group

*** PREVIEW USE ONLY *** REPAIR ORDER

760826



NC

BUILDER: Zancor Homes

JOB SITE: Belle Aire Shores PH3

Customer Code:

Job Number: 18648 Board Area:8

COMPLAINT DATE: 05/03/24

LOT: 357W

INSTALLER:

SCHEDULED DATE: MAY 9 11 41 AM

OWNER NAME:

OWNER TEL:

OWNER ADDR:

REPAIR DURATION:

ACCESS NOTES:

REPAIR TYPE: PDI

REPAIRMAN:

BUILDER WO#

BUILDER PO#:

PO Required: NO Inspection Req'd: NO

ORIGINAL WO#: 735730

REPAIR DESC: Seam visible in Bedroom 2
Seam visible in Main Hall
Seam visible in Bedroom 3
Carpet bubbled in middle of Bedroom 3
Seams visible in Bedroom 4
Seams visible in Master Bedroom

PROD INFO/NOTES:

PROD ORDERED:

SUPPLIER:

PO#:

DUE: / /

INSTALLER'S SIGNATURE: _____

SUPER'S/OWNER'S SIGNATURE: _____

DATE: 15th May 2024

NOTE* Please have this memo signed by the owner or site super upon completion.**

WARNING

THINK SAFETY - ALWAYS WEAR
YOUR SAFETY SHOES AND HARDHAT

INSTALLER SIGNATURE

DATE



HEAD
PROTECTION



FOOT
PROTECTION



CLASS A
Compressed
Gas



CLASS B
Flammable and
combustible
material



CLASS C
Oxidizing
material



CLASS D
Materials causing
immediate and
serious toxic
effects



CLASS D
Materials causing
other toxic effects



CLASS D
Bio hazardous
Infectious Material



CLASS E
Corrosive
Material



CLASS F
Dangerously
Reactive
Material