

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

7630 AIRPORT ROAD, MISSISSAUGA, ON L4T 4G6 TEL (905) 672-1233 FAX (905) 672-1076 WO # W216301 Pack Slip:262820

Service Date: Jun 07, 2024

Priority: Normal Status: SCHEDULED **BUILDER** Customer: N000690 City: WASAGA BEACH Received: May 06, 2024 Name: ZANCOR RIVERS EDGE Service Phone(s): Time: Service Fax: Site Phone: Order: D392854-1 Site Fax: Lot#: 283 Phase: RESIDENT INFORMATION Home Owner Name: N/A Address: Home Phone(s): Work Phone(s): Cell Phone(s): Email(s): **LINKED ORDER INFORMATION (D392854-1)** Customer: N000690 ZANCOR RIVERS EDGE Lot #: 283 Model: 50-5 (RR UPG) (CB)/LOB Phase: SERVICE INSTRUCTIONS KITCHEN--CHECK SEAL AROUND WINDOW AT BOTTOM EXTERIOR SIDE Problem Description: **CHARGEABLES** Material \$ Material \$ Labour \$ Labour \$ P.O.#: Cause: Solution: Date Completed: Approved: Service Signature: STEVE



Service Department <servicedept@newmar.com>

Fwd: LIST TO COMPLETE RIVER'S EDGE

1 message

Melissa Green <mgreen@newmar.com>

To: Service Department <servicedept@newmar.com>

Mon, May 6, 2024 at 10:03 AM

----- Forwarded message -----

From: Mary lelpo <mary@zancorhomes.com>

Date: Mon, May 6, 2024 at 9:58 AM

Subject: LIST TO COMPLETE RIVER'S EDGE

To: service@newmar.com <service@newmar.com>, sfacey@newmar.com <sfacey@newmar.com>,

mgreen@newmar.com <mgreen@newmar.com>

Here is an updated list to complete.

121	KITCHENWINDOW FRAME CRACKED AT LOWER RIGHT SIDE
122	DENWINDOW SEAL DAMAGED AT OPERABLE WINDOW
122	ADJUST FRONT DOORSNOT FLUSH ON TOP
283	KITCHENCHECK SEAL AROUND WINDOW AT BOTTOM EXTERIOR SIDE

Thanks, Mary



Mary lelpo

mary@zancorhomes.com

Finishing Supervisor

River's Edge/Shoreline Wasaga Beach

Head Office P:905-738-7010 F:905-738-5948

221 North Rivermede Road - Concord, ON L4K 3N7

**** ALL NEW SERVICE REQUESTS ARE TO BE SENT TO servicedept@newmar.com ******

Thank you 😈

Melissa Green

Customer Service Coordinator

