

Zancor Homes (Caledon) Ltd.

Work Order

Warranty Services Phone: (905) 738-7010

Fax: (905) 738-5948

Closing Date: 18Apr24

Address: 12354 Mclaughlin Road

Caledon, ONTARIO L7C 4L7

Location: Caledon Club - Phase: 1B - Lot: Block 178 - Unit 4

Today's Date:

Contact(s): RAMANDEEP VERMA - Cell: (647) 641-2234 - (RAMANDEEPVERMA@GMAIL.COM)

NAVEEN VERMA - Cell: (647) 721-3460 - (NAVEENVERMA425@GMAIL.COM)

Sonia Verma - Cell: (647) 204-6757 - (sonia.verma521@gmail.com)

Rupinder Verma

RAMANDEEPVERMA@GMAIL.COM

Company: ZANCOR CALEDON-SITE LABOUR

Attention:

Telephone:

Please Complete the following items:

DAI	Туре	Issue	Appt. Date/Time	Notes
175049	PDI	FOYER/HALL- NOTE:~DENT ON RIGHT OPERATING		Done

Date Completed: 22

Homeowner Signature:

has been completed in a workman like manner. The Homeowner acknowledges and accepts all work

Date Completed: JUNE

Trade &/or Service Tech.

Signature:

Print Name: Jesse Sima

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

Zancor Homes (Caledon) Ltd. Warranty Services

Work Order

Phone: (905) 738-7010

Fax: (905) 738-5948

Closing Date: 06Jun24

Address: 79 Camino Real Drive

Location: Caledon, Ontario L7C 4L9
Caledon Club - Phase: 1B - Lot: Block 191 - Unit 6

Today's Date: 03Jun24

Email: Contact(s): Abdul Munim Sheikh - Home: (647) 299-2609 - (munim.sh@gmail.com) munim.sh@gmail.com

Company: ZANCOR CALEDON-SITE LABOUR

Attention: Telephone:

Fax:

DAI Type li	Please Complete the follow
sue	ng items:
Appt.	

176750	176780	176779	DAI
PDI	PDI	PDI	Туре
BASEMENT- NOTE:~INSPECT FOUNDATION WALL INSIDE COLD ROOM LEFT SIDE CRACK FOR WIDER THEN 4MM	BASEMENT- NOTE:~INSPECT HOLE AT JOIST BELOW GAS PIPE TO FRONT OF HOUSE LARGER THAN 2 1/2 INCHES AS PER INSPECTOR.	BASEMENT- NOTE:~INSPECT HOLE BELOW GAS, PROOFING AND SHIM ABOVE CONCRETE WALL RIGHT OF ELECTRICAL PANEL IN BASEMENT AND LEFT OF FURNACE.	Issue
			Appt. Date/Time
RE-TRADE MOF	VELCAN SENT SPECS FOR DRUML THAN DIST'S	3MDQ	Notes
	-		

176766	176765	176764	176756	176753	176781
PDI	PDI	PDI	PDI	PDI	PDI
Note~SEE PHOTOS OF GREEN TAPE THROUGHOUT	Note~GREEN TAPE THROUGHOUT.	Note~GREEN TAPE THROUGHOUT.	FOYER/HALL- NOTE:~INSTALL DOOR STOP FOR FIXED OPERATING FRONT DOOR	LIVING ROOM- WIND OWS~REPAIRED JAMB UNFINISHED LEFT OF OPERATING WINDOW	EXTERIOR- NOTE:~REMOVE SHIM AT LENTIL AT FRONT PORCH.
			DOWE	ENO CI	DONE

Signature: Samme	
Trade &/or Service Tech.	Date Completed: June 6/24
has been completed in a workman like manner.	
The Homeowner acknowledges and accepts all work	
Homeowner Signature:	Date Completed:

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

Print Name:

Simols

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

Laura Polsinelli

Anthony Riccardi

Sent: From:

Monday, June 3, 2024 8:24 AM

Laura Polsinelli; Nathan Simas; Gisella Fiore

Subject: Blk 191-6

thru subfloor, have Jesse remove shim and firestop holes. Laura/Nathan, please meet wit home lumber to get a detail of holes thru joist. As for shim and holes

Thank you

Anthony Riccardi



Concord, Ontario L4K 3N7 221 North Rivermede Road

T. 905.738.7010 F. 905.738.5948

disclosure or distribution is prohibited. If you are not the intended recipient, please reply to the sender by email and destroy all copies of the original message. intended recipient(s) and may contain confidential and privileged information. Any unauthorized review, use, CONFIDENTIALITY NOTICE: This email message, including any attachments, is for the sole use of the

From: Gisella Fiore < Gisella @zancorhomes.com>

Sent: Monday, June 3, 2024 8:19 AM

To: Anthony Riccardi <anthony@zancorhomes.com>

Subject: HOME LUMBER

Laura Polsinelli

From: Jeff Jenkins <jjenkins@velcan.com>

Sent: Laura Polsinelli Thursday, June 6, 2024 9:55 AM

<u>...</u> Subject: 5 Attachments: RE: Blk 191-6 Nathan Simas

SKM_300i24060610450.pdf

Good morning Laura, please see attached information.

It is hard to tell the size of hole made from the picture, but I believe I have the correct joist and location identified.

As long as there is no damage to the flange, I don't believe there should be any remedial work required

Hope this helps, but if not please feel free to reach out again.

Cheers,



From: Laura Polsinelli <laura@zancorhomes.com>

Sent: Thursday, June 6, 2024 9:23 AM

To: Jeff Jenkins < jjenkins@velcan.com>

Cc: Nathan Simas < nathan@zancorhomes.com >

Subject: Re: Blk 191-6

Good morning Jeff

for correction. Just wanted to follow up with this request. This home is closing and I need to have documentation of the visit and steps

Sent from my iPhone Zancor Homes-Caledon Club Laura Polsinelli Thank you,

On Jun 3, 2024, at 1:35 PM, Laura Polsinelli laura@zancorhomes.com wrote:

Good afternoon Jeff

accurate repair information to provide to the HO for PDI and the below was called out. We would like to ensure that we have the correct and Can I please have someone come to site to review this. The HO had an inspector come in

Thank you Laura Polsinelli