



NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W24366
Pack Slip:5344

Service Date: May 31, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030

Name: ZANCOR THE BRANCH CONDOS

Service Fax:

Site Fax:

City: OAKVILLE

Service Phone(s):

Site Phone: (416) 566-2066

Lot#: 7F-CRT

Received: May 08, 2024

Time:

Order: H801508-1

Phase: 721

RESIDENT INFORMATION

Home Owner Name:

Home Phone(s):

Cell Phone(s):

Address:

Work Phone(s):

Email(s):

LINKED ORDER INFORMATION (H801508-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS

Lot #: 7F-CRT

Phase:

House Model: 7TH FLOOR COURTYARD

Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #176101 - PDI - MASTER BEDROOM - GENERAL - WINDOW CRANK NOT INSTALLED AT OPERATING WINDOW

2) INSPECT SCRATCHES ON RIGHT AND LEFT SIDE MULIN *Completed*

3) INSPECT BLACK SCUFF ON SLIDING DOOR *Completed*

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE WINDOW CRANK	MASTER BEDROOM	OTHER - REPLACEMENT PARTS	0 X 0	BONE WHITE UC113812	1

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

P.O.#:

Cause:

Solution:

Date Completed:

Approved:

Time:

Service Signature:

EESAA