

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076

WO # W21462 Pack Slip:4980 Service Date: Feb 05, 2024

HI-RISE

Priority:	Normal		Status:	COUEDIN ED			
BUILDER	and the second s		Otatus.	SCHEDULED			
Customer:	mer: 8030030		City:			***************************************	
Name:	ZANCOR THE BRANCH CO	ONDOS	Service Phone(s):	OAKVILLE	Received:	Jan 15, 2024	
Service Fax:			Site Phone:	(416) 566 2000	Time:		
Site Fax:			Lot#:	(416) 566-2066 3F-CRT		H801504-1	
RESIDENT INFORMATION			SI -CK1		Phase:	Phase: 347	
Home Owner	Name: JASON IVAN SAJK	0	Address:	2450.01			
Home Phone(s): 289-242-6390			Work Pho	2450 OLD BRONTE ROAD, SUITE 347		UITE 347	
Cell Phone(s):			Email(s):	Lsajural@hotmail.com			
LINKED OR	DER INFORMATION (H80	1504-1)	Eman(3).	Lsajurai	@notmail.com	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
Customer: 8	B030030 ZANCOR THE BRAI	NCH CONDOS					
	BF-CRT	Phase:	,		3RD FLOOR COURT	YARD	
SERVICE IN	STRUCTIONS	The second secon		Elevation:			
EXAMINE AND	O CORRECT:	***************************************					
DAI #171606 - INSTALLED OI PARTS REQI	Programme and the second secon	WINDOWS - S	SCREEN AND WINI	DOW CRANK NO	T INSTALLED - NEW	CRANK	
LN Item Descri		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~					
	WINDOW CRANK	Location MASTER BEDROOM	Specification OTHER - REPLACEMENT PARTS	Size 0 X 0	Options BONE WHITE UC11	Qty 13812 1	
113 NEWMAR 3	ALUMINUM AWNING	WBCH3-WC N13		27 7/8 X 18 3/4	BONE WHITE UC11	3812 1	
Address Label	S	<u> </u>	10	******			
BCH-3F-1-35		U		***************************************			
Problem Descrip	otion:					tan managan kalan managa kan managan ka mana	
Warranty			CHARC	EABLES			
Material \$			Material \$	LABLES			
Labour \$			Labour \$				
	A (/ /		P.Ο.#:				
Cause:	Not Lome	r ac	ess Trefalle	ed screen	Not home	6 SIGN	
Solution:							
Date Complete	ed:		Approve	ed:	1		
Zeelkumar Patel \ 02-0	24 000 4 4 4 7 2			J. J			
-conunial Mater 1 119-1	11-21124 11:59 am						

Time:	Service Signature:	
	STEVEN	