



NEWMAR WINDOW MFG. INC.
ALPHA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076

WO # W21766
Pack Slip: 5332

Service Date: Feb 05, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer: 8030030

Name: ZANCOR THE BRANCH CONDOS

Service Fax:

Site Fax:

City: OAKVILLE

Service Phone(s):

Site Phone: (416) 566-2066

Lot#: 8F-CRT

Received: Jan 23, 2024

Time:

Order: H801509-1

Phase: 819

RESIDENT INFORMATION

Home Owner Name: NIROJAN & ELAYATHAMBY SIVANESA

Address: 2450 OLD BRONTE ROAD, OAKVILLE, ONTARIO

Home Phone(s):

Cell Phone(s): 647-607-6357, 416-832-5760

Work Phone(s):

Email(s): NIRO94_6@HOTMAIL.COM

LINKED ORDER INFORMATION (H801509-1)

Customer: 8030030 ZANCOR THE BRANCH CONDOS

Lot #: 8F-CRT

Phase:

House Model: 8TH FLOOR COURTYARD

Elevation:

SERVICE INSTRUCTIONS

GOES WITH WO21181

EXAMINE AND CORRECT:

DAI #171477 - PDI - 1) Wrong size MISSING BALCONY SCREEN 2) Done SLIDER NOT LOCKING

DAI #171476 - PDI - GENERAL COMMENTS - SCREEN RIPPED OPERATING WINDOW LIVING ROOM (BRING BACK TO SHOP FOR REMESH) Done

DAI #171478 - PDI - GENERAL COMMENTS - MULLION DAMAGED TOP LEFT IN LIVING ROOM SLIDING DOOR - COMP ON JAN 31ST

DAI #171482 - PDI - GENERAL COMMENTS - SCRATCHES BY CRANK AND ABOVE OPERATING WINDOW MASTER BEDROOM - COMP ON JAN 31ST

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
963	NEWMAR ALUMINUM AWNING	WBCH8-WC	SCREENS	27 7/8 X 18 3/4	BONE WHITE UC113812	1
	Brought back to shop for remesh	S24				

Address Labels

BCH-8F-28-44*

Completed

Problem Description:

☐ Warranty

Material \$

Labour \$

☐ CHARGEABLES

Material \$

Labour \$

Cause:

This work order is done. WO# 21181 has patio screen on it

Solution:

Date Completed: Feb. 05 / 2024

Approved: _____

Time: _____

Service Signature: 
STEEVEN