



706 94 92

NEWMAR WINDOW MFG. INC.
ALPA LUMBER GROUP8 EDVAC DRIVE, BRAMPTON ON L6S 5P2
TEL (905) 672-1233 FAX (905) 672-1076WO # W21451
Pack Slip:5187

Service Date: Feb 06, 2024

Priority: Normal

Status: SCHEDULED

BUILDER

Customer:	8030030	City:	OAKVILLE	Received:	Jan 12, 2024
Name:	ZANCOR THE BRANCH CONDOS	Service Phone(s):		Time:	
Service Fax:		Site Phone:	(416) 566-2066	Order:	H801507-1
Site Fax:		Lot#:	6F-CRT	Phase:	645

RESIDENT INFORMATION

Home Owner Name:	Address:
Home Phone(s):	Work Phone(s):
Cell Phone(s):	Email(s):

LINKED ORDER INFORMATION (H801507-1)

Customer:	8030030 ZANCOR THE BRANCH CONDOS	House Model:	6TH FLOOR COURTYARD
Lot #:	6F-CRT	Phase:	Elevation:

SERVICE INSTRUCTIONS

INVESTIGATE AND CORRECT

DAI #170844 - PDI - MASTER BEDROOM - WINDOW HANDLE NOT INSTALLED - DONE

DAI #170846 - PDI - LIVING ROOM - REPLACE BALCONY SCREEN - RIPPED

PARTS REQUIRED

LN	Item Description	Location	Specification	Size	Options	Qty
10	REQUIRE WINDOW CRANK COMPLETED	MASTER BEDROOM	OTHER - REPLACEMENT PARTS	0 X 0	BONE WHITE UC113812	1
103	PURCHASED PATIO DOOR 2 Screen brought back to shop for remesh COMPLETED	WBCH6-WC N6	SCREENS	35 7/16 X 84 1/16	STEEL-CITY SILVER UCFX12200 LEFT	1
Address Labels BCH-6F-1-28*						
104	53 - ADAPTOR PART 2 0 Require Profile #53 all round the patio door	TBA	OTHER - REPLACEMENT PARTS	120	BONE WHITE UC113812	4

IDONB

Problem Description:

☐ Warranty☐ CHARGEABLES

Material \$ _____

Material \$ _____

Labour \$ _____

Labour \$ _____

P.O.#: _____

Cause: _____

Solution: _____

Date Completed: _____

Approved: _____



Time: _____

Service Signature: _____

KHEM