



Zancor Homes (Parkview) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 14Jul22

Address: 6731 Thickson Road North
Whitby, Ontario L1M 0M3

Location: Now Towns In Brooklin - Phase: 1 - Lot: Unit 1 (Block 1)

Today's Date: 03Sep24

Contact(s): Velalagan Rajendram - Cell: (416) 520-7230 - (rosan2nisha@gmail.com)
Saranka Rajendram - Cell: (647) 291-6961 - (saranka.sr20@gmail.com)

Email: rosan2nisha@gmail.com

Company: Promark Aluminum LTD.

Attention: Kamar Kuyumju - Cell: 416-576-0236

Telephone: (905) 857-5692

Fax: (905) 857-5961

Please Complete the following items:

DAI	Type	Issue		Appt. Date/Time	Notes
178519	2 Year	Exterior- General- One of the panels that covers the bottom of the deck that is above the garage has came off in February from a storm and is still hanging there. This has caused the other panels to loosen because there are no nails to secure the			
178520	2 Year	Exterior- General- The bottom panels of the balcony that is over the front entrance door are also loose like the panels that cover the deck over the garage, and one is starting to come off since it does not seem to have nails holding it in place			

Date Completed: _____

Homeowner Signature: _____

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed: Sept 18, 2024

Trade &/or Service Tech.

Signature: Davor

Print Name: Davor

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Now Towns In Brooklin - Phase: 1 - Lot: Unit 1 (Block 1)

178519 - 1 - IMG_6236 - One of the panels that covers the bottom of the deck that is above the garage has come off in February from a storm and is still hanging there. This has caused the other panels to loosen because there are no nails to secure the

