

NEWMAR WINDOW MFG. INC. ALPA LUMBER GROUP

8 EDVAC DRIVE, BRAMPTON ON L6S 5P2 TEL (905) 672-1233 FAX (905) 672-1076 WO # W28839 Pack Slip:5968

Service Date: Nov 01, 2024

SCHEDULED Status: Normal Priority: **BUILDER** Oct 31, 2024 Received: **OAKVILLE** City: Customer: 8030030 Time: Service Phone(s): ZANCOR THE BRANCH CONDOS Name: Order: H801168-1 (416) 566-2066 Site Phone: Service Fax: Phase: 717 7TH FLOOR Lot#: Site Fax: RESIDENT INFORMATION 2450 OLD BRONTE ROAD, OAKVILLE, Address: Home Owner Name: GEOFFERY FARROW ONTARIO, Work Phone(s): Home Phone(s): GFARROW@HOTMAIL.COM Email(s): Cell Phone(s): 905-510-8560 **LINKED ORDER INFORMATION (H801168-1)** House Model: 7TH FLOOR 8030030 ZANCOR THE BRANCH CONDOS Customer: Elevation: Phase: 7TH FLOOR Lot #: SERVICE INSTRUCTIONS INVESTIGATE AND CORRECT DAI #179275 - PDI - MASTER BEDROOM - HANDLE LOOSE SCRATCH ON MULLION SCRATCH ABOVE OPERATING WINDOW Problem Description: CHARGEABLES Warranty Material \$ Material \$ Labour \$ Labour \$ P.O.#: Cause: Solution: Approved: Date Completed: _ Service Signature: Time: