Enrollment:

Purchaser Name: George Roswell

Jasmine Roswell

Phone Res:

Phone Bus: (647) 409-8282

Closing Date: July 31, 2025

Inspector: Gisella Fiore

ZANCOR HOMES PDI Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 702 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 702

Municiaplity:

Inspection Date: March 07, 2025

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

Page 1 of 2

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- · Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- · Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- · Faucets: Kitchen, bathroom, laundry room
- · Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- · Gas fireplaces, incl.circulation fans, if provided
- · Heat Recovery Ventilation system, if provided
- Heating system
- · Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

MASTER ENSUITE BATH				
VANITY CABINETS	ADJUST ALL CABINET AND DRAWER THROUGHOUT MASTER ENSUITE.			
NOTE:	GROUT REQUIRED AT TILE BEHIND DOOR LARGE GAP AT BASEBOARD.			
	INSTALL LIGHT FIXTURE AT VANITY.			
MASTER BEDROOM				
NOTE:	CRACKED TILE BELOW DOOR JAMB RIGHT SIDE.			
	BACK FLOORING AT WINDOW 6-8 PLANKS FROM WALL FOR WATER DAMAGE			
	REPLACE TRIM/DRWALL RIGHT AND LEFT SIDE.			
	MISSING WINDOW SCREEN			
	ADJUST CLOSET DOOR NOT LATCHING			
LIVING ROOM				
NOTE:	INSTALL HANDLE AT BULK IN LIVING ROOM			
	INSTALL SHOEMOLD NOT INSTALLED AT STEP.			
WINDOWS	ADJUST SLIDING DOOR AND SCREEN AT BALCONY TO LARGE BALCONY.			
KITCHEN				
CABINETS	ADJUST UPPER CABINET ABOVE HOODFAN.			
	INSTALL ALL UPPER SHELVING MISSING 2) CHIP AT BOTTOM LET CABINET			
NOTE	SHELF LEFT OF SINK.			
NOTE:	DISH WASHER NOT CONNECTED AND KICK PLATE NOT INSTALLED.			
	MISSING KICKPLATE AT ISLAND AND FRIDGE.			
	ADJUST CABINE ABOVE FRIDGE 2) FILLER GABLE RIGHT OF FRIDGE GAP. 2)			
	BOTTOM RIGHT FRIDGE GABLE PEELING			
	CRACKS TRIM X2 BELOW SLIDING DOOR BEHIND ISLAND			
	INSPECT GAPS AT HARDWOOD FLOORING BEHIND ISLAND LIFTING			

Enrollment:

Purchaser Name: George Roswell

Jasmine Roswell

Phone Res:

Phone Bus: (647) 409-8282

Closing Date: July 31, 2025

Inspector: Gisella Fiore

ZANCOR HOMES

Page 2 of 2

Vendor / Builder:

Project: Zancor Oakville Ltd.

Lot / Phase: 702 / 1

Plan:

Address: 2450 Old Bronte Road, Suite 702

Municiaplity:

Inspection Date: March 07, 2025

LAUNDRY ROOM			
NOTE:	ADJUST DOORS TO CLOSET SQUEAKING / BOWED AT BASE INSPECT AND		
	CONFIRM IF SHOULD BE REPLACED.		
	INSTALL WATER SHUTOFF.		
MAIN BATHROOM			
NOTE:	MISSING LIGHT FIXTURE AT VANITY.		
VANITY CABINETS	NAIL HOLES IN VANITY AT GABLE BELOW		
	INSPECT TUB. HOT WATER NOT GETTING HOT.		
FOYER/HALL			
NOTE:	CRACK/CHIP AT 1ST AND SECOND PLANK FROM MAIN BATH		
	INSPECT CURVED WALL INFRONT OF CLOSET LEFT OF FRONT DOOR.		
BEDROOM #3		_	
NOTE:	SCRATCH X2 A WINDOW CRANK.		

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

George Roswell
Purchaser's Name (print)
Purchaser's Signature
Purchaser's Name (print)
Purchaser's Signature
Gisella Fiore
Designate's Name (print)
Designate's Signature
Inspector's Name (print)
Inspector's Signature