Zancor Homes (Caledon) Ltd. Warranty Services

Work Order

Fax: (905) 738-5948 Phone: (905) 738-7010

Address: Closing Date:

08Jan24

Location: 12360 McIaughlin Road Caledon, Ontario L7C 4L7 Caledon Club - Phase: 1B - Lot: Block 177 - Unit 3

13Mar25

Today's Date:
Contact(s): Saadia Rajput - Cell: (647) 616-6066 - (saadia@iprorealty.com) saadia@iprorealty.com

Email:

Zancor -Caledon

Company: Attention:

Telephone:

Fax:

180486 180487	1804		180483	180482	180481	180479	180478	DAI
		86	83	82	84	79		
1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	Туре
Main Bathroom- General- Plug not	Basement- General- Large foundation cracks in floor	Other- General- Paint needs to be redone throughout	Stairs- General- Gap on the staircase	Basement- General- Large cracks in foundation	Exterior- General- outside railing on patio is damaged	Exterior- General- Gap in garage door rail	Exterior- General- Damaged Railing	Issue
1	1		1	7	1	1		
								Appt. Date/Time
A	20	\sim	2	R	200	Radired to Garay	BRITON -3	Notes

180493	180492
1 Year	1 Year
Stairs- General- Steps are rough and have a water mark on them. They feel like the have bt been sanded and they are a different colour than the rest of the steps.	Main Bathroom- General- Metal trim is still damaged as well as the hardwood from the tile to the hardwood in the ensuite
<	
	,
8	KRUSOOK AN AND FCH SAME TI'HE
	1 Year Stairs- General- Steps are rough and have a water mark on them. They feel like the have bt been sanded and they are a different colour than the rest of the steps.

Date Completed: MIKCIF 13/6

Homeowner Signature:

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed:

Trade &/or Service Tech.

Signature:

Print Name:_

signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367. adhere to the appointment you have scheduled. Your service representative must have this form appointment time or date appear (below) on this form, it is your responsibility to arrange and Please schedule your Service Department to complete work on the above Lot. Should no

applied to the Company listed above. it's group of companies) the right to carry out any and all repairs. All costs incurred will be Failure to comply with this request within 10 business days will give Zancor Homes (and

Outstanding Deficiencies Caledon Club - Phase: 1B - Lot: Block 177 - Unit 3

06Feb25	<u>06Feb25</u>	<u>06Feb25</u>	<u>06Feb25</u>	06Feb25	<u>06Feb25</u>	06Feb25	06Feb25	<u>06Feb25</u>	06Feb25	<u>06Feb25</u>	<u>06Feb25</u>	06Feb25	06Feb25	06Feb25	<u>06Feb25</u>	06Feb25	Date Reported
1 Year	l Year	l Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	1 Year	Type
17	16	15	14	13	12	11	10	9	∞	7	6	٥.	4	w	2	<u> </u>	Number
Den- General- Nail pops through first second and third floors	Stairs- General- Steps are rough and have a water mark on them. They feel like the have bt been sanded and they are a different colour than the rest of the steps.	Main Bathroom- General- Metal trim is still damaged as well as the hardwood from the tile to the hardwood in the ensuite	Main Bathroom- General- Plug not secured	Master Bedroom- General- Crack in drywall	Stairs- General- Crack in drywall	Kitchen- General- Screen door does not lock	Basement- General- Large foundation cracks in floor	Other- General- Paint needs to be redone throughout	Main Bathroom- General- Cracked tile in bathroom entryway	Main Bathroom- General- Sharp metal plate, it is also bent-noted at 30 day T MOLD CHIPPED AFTER REPLACED	Stairs- General- Gap on the staircase	Basement- General- Large cracks in foundation	Exterior- General- outside railing on patio is damaged	Exterior- General- Garage door has a prominent draft coming in.	Exterior- General- Gap in garage door rail	Exterior- General- Damaged Railing	Deficiency Description
Foremont Drywall 180494	Zancor - Caledon 180493	Zancor - Caledon 180492	Zancor - Caledon 180491	Foremont Drywall 180490	Foremont Drywall 180489	Newmar 180488	Zancor - Caledon 180487	Zancor - Caledon 180486	AV Classic 180485	<u>First</u> <u>Canadian</u> <u>Hardwood</u> 180484	Zancor - Caledon 180483	Zancor - Caledon 180482	Zancor - Caledon 180481	Abbey Overhead Doors Inc. 180480	Caledon 180479	Zancor - Caledon 180478	Trade Assigned
Add	Add	Add	<u>Add</u>	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add	Add Trade
NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	NoAppoint.	Add Appointment
	1		1				1	1			1	1	1				Item Completed
M			a	2	Sec		28	8	CL		2	X	R	SIC			Initial

Interval 29 Foyer- General- MUD ROOM DOOR TO BE ADJUSTED

13Mar25

Newmar 181071

Add

NoAppoint.

Homeowner Signature:

The Homeowner acknowledges and accepts that all initialled work has been completed in a workman like manner to their satisfaction.

Zancor Service Technician: