



Zancor Homes (Wasaga River) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date: 07Nov23

Address: 158 Rosanne Circle

Wasaga, Ontario

Location: Rivers Edge - Phase: 1 - Lot: 117

Today's Date: 12May25

Contact(s): Alfonso Licata - Home: (416) 804-8340 - (allicata@bgs.ca)

Pina Licata - Home: (416) 418-9528 - (pina@wsibldm.com)

Email: allicata@bgs.ca

Company: Wasaga Zancor Warranty Service

Attention:

Telephone: (705) 428-6483

Fax: (705) 428-6484

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
179663	1 Year	Exterior- General- At the front and back of the house the cladding/aluminum is dented in several places, and back garden doors, the aluminum is slivered- Svc touch up as courtesy - TO BE COMPLETED IN THE SPRING	16May25 /am	8-12 <i>DONE</i>
179664	1 Year	Exterior- General- FRONT ENTRY DOOR AND BACK GARDEN DOORS NEED TO BE PAINTED, ALOT OF MARKS-Streak marks in paint at balcony dodor - TO BE COMPLETED IN THE SPRING	16May25 /am	8-12 <i>DONE</i>

Date Completed: _____

Homeowner Signature:  _____
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____


Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no
appointment time or date appear (below) on this form, it is your responsibility to arrange and
adhere to the appointment you have scheduled. Your service representative must have this form
signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and
it's group of companies) the right to carry out any and all repairs. All costs incurred will be
applied to the Company listed above.**

Rivers Edge - Phase: 1 - Lot: 117

179663 - 1 - 12 - At the front and back of the house the cladding/aluminum is dented in several places, and back garden doors, the aluminum is slivered- Svc touch up as courtesy - TO BE COMPLETED IN THE SPRING



179663 - 2 - 12 - At the front and back of the house the cladding/aluminum is dented in several places, and back garden doors, the aluminum is slivered- Svc touch up as courtesy - TO BE COMPLETED IN THE SPRING



179664 - 1 - 12 - FRONT ENTRY DOOR AND BACK GARDEN DOORS NEED TO BE PAINTED, ALOT OF MARKS- Streak marks in paint at balcony dodor - TO BE COMPLETED IN THE SPRING

