Enrollment: 224

Purchaser Name: Bruce C Tasios

Phone Res: (416) 407-8077

Phone Bus:

Closing Date: June 09, 2025

Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 224 / 1

Plan:

Address: 2075 King Road, Unit 224

Municiaplity:

Inspection Date: May 16, 2025

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
NOTE:	CHIP ON UPPER GABLE LEFT OF MICROWAVE	
	KICKPLATE NOT INSTALLED BELOW FRIDGE	
	UPPER SHELF NOT INSTALLED LEFT OF MICROWAVE	
	SECURE SHELF RIGHT OF MICROWAVE NOT FLUSH WITH GABLE	
	ADJUST UPPER GABLE RIGHT OF MICROWAVE - NOT FLUSH LIKE LEFT SIDE	
BEDROOM #2		
NOTE:	ADJUST CLOSET DOORS NOT FLUSH AT TOP	
GENERAL COMMENTS	S	
NOTE:	MAIN BATH - INSTALL TOILET PAPER HOLDER ON VANITY AND INSTALL TOWEL BEHIND DOOR.	
	HEIGHT MAY VARY MASTER ENSUITE - INSTALL TOILET PAPER HOLDER ON VANITY AND	
	TOWEL BEHIND DOOR. HEIGHT MAY VARY	
MASTER ENSUITE BA	тн	
NOTE:	INSPECT HRV DOOR AT CEILING SPRINKLER CAP ON TOP OF EDGE	
	TMOLD TO BATHROOM ENTRANCE SHORT	
LIVING ROOM		
NOTE:	ADJUST BALCONY DOOR NOT LOCKING	

Enrollment: 224
Purchaser Name: Bruce C Tasios

Phone Res: (416) 407-8077 Phone Bus:

Closing Date: June 09, 2025 Inspector: Gisella Fiore



Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 224 / 1

Plan:

Address: 2075 King Road, Unit 224

Municiaplity:

Inspection Date: May 16, 2025

ella Fiore Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. Bruce C Tasios Purchaser's Signature Purchaser's Name (print) Purchaser's Name (print) Purchaser's Signature N. Juneals Gisella Fiore Inspector's Name (print) Designate's Name (print) Designate's Signature Inspector's Signature May 16, 2025 Date (YYYY/MM/DD) 2025/05/16