Enrollment: 420

Purchaser Name: PARMANAND BEETAN

Phone Res: (905) 867-8264

Phone Bus:

Closing Date: June 10, 2025

Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 420 / 1

Plan:

Address: 2075 King Road, Unit 420

Municiaplity:

Inspection Date: June 02, 2025

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
NOTE:	CHIP ON FRIDGE PANEL/FREEZER AND CABINET ABOVE FRIDGE CHIPPED.	
	LOWER LEFT LEFT OF FRIDGE SHELVE NOT INSTALLED	
	DISHWASHER NOT CONNECTED.	
	DW PANEL NOT INSTALLED. / UPPER LEFT CABINET LEFT OF MICROWAVE SCRATCHED.	
	FILM AT EDGE OF BANK OF DRAWERS LEFT ON CABINETS.	
MAIN BATHROOM		
NOTE:	INSTALL TOILET PAPER HOLDER ON VANITY AND TOWEL RACK ABOVE TOILET	
	MIRROR NOT INSTALLED	

Enrollment: 420

Purchaser Name: PARMANAND BEETAN

Phone Res: (905) 867-8264

Inspector: Gisella Fiore

Phone Bus:

Closing Date: June 10, 2025

ZANCOR HOMES Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 420 / 1

Plan:

Address: 2075 King Road, Unit 420

Municiaplity:

Inspection Date: June 02, 2025

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. PARMANAND BEETAN Purchaser's Name (print) Purchaser's Signature Purchaser's Name (print) Purchaser's Signature Gisella Fiore Designate's Signature Inspector's Name (print) Designate's Name (print) Inspector's Signature Date (YYYY/MM/DD) 2025/06/02 June 02, 2025