Enrollment: 443

Purchaser Name: GEORGE CAMERON KELLY

GRAHAM ALAN KELLY

Phone Res: (289) 716-2558 Phone Bus: (416) 662-4891 HOMES

Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 443 / 1

Plan:

Address: 2075 King Road, Unit 443

Municiaplity:

Inspection Date: June 12, 2025

Closing Date: June 17, 2025 Inspector: Gisella Fiore

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN		
NOTE:	DISHWASHER PANEL NOT INSTALLED.	
	DISHWASHER DOOR SCRATCHED.	
	DAMAGE VALANCE RIGHT OF MICROWAVE 2) CHIP ON UPPER RIGHT C CABINET ABOVE DISHWASHER	
	CHIP ON UPPER LEFT CABINET ABOVE SINK	 - <u></u> -
	CHIP ON UPPER RIGHT CABINET LEFT OF FRIDGE AT TOP.	
	SMALL CHIP BOTTOM EDGE CORNER RIGHT OF SINK AT FILLER 2) SMALL CHIP AT BOTTOM OF FRIDGE PANEL	
	INSTALL KICKPLATES BELOW BANK OF DRAWER AND SINK 2) LARGE CHIP AT GABLE LEFT OF BANK OF DRAWER.	
-	ADJUST STOVE DRAWER ON ANGLE.	
MAIN BATHROOM		
-	INSTALL BATH ACCESSORIES ON CABINET/ABOVE TOLIET	
	SCRATCH CABINET BELOW SINK RIGHT SIDE	
	ADJUST HRV DOOR AT CEILING	
	REPLACE LEFT WINDOW HANDLE DAMAGED/ ADJUST SCREEN RIGHT SIDE.	
FOYER/HALL		
-	PEEP HOLE NOT INSTALLED	

Enrollment: 443

Purchaser Name: GEORGE CAMERON KELLY

GRAHAM ALAN KELLY

 Phone Res:
 (289) 716-2558

 Phone Bus:
 (416) 662-4891

 Closing Date:
 June 17, 2025

 Inspector:
 Gisella Fiore

ZANCOR

Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 443 / 1

Plan:

Address: 2075 King Road, Unit 443

Municiaplity:

Inspection Date: June 12, 2025

Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf. I have inspected my new home and I agree that the description of the items listed on this form are accurate. (dulls GEORGE CAMERON KELLY GRAHAM ALAN KELLY Purchaser's Signature Purchaser's Signature Purchaser's Name (print) Purchaser's Name (print) Gisella Fiore Inspector's Signature Designate's Name (print) Designate's Signature Inspector's Name (print) Date (YYYY/MM/DD) 2025/06/12 June 12, 2025