

Enrollment: 346
Purchaser Name: GIANLUCA FRISOLI
Phone Res: (647) 638-6115
Phone Bus:
Closing Date: July 03, 2025
Inspector: Gisella Fiore



Vendor / Builder:
Project: Zancor Homes (King Cort) Ltd.
Lot / Phase: 346 / 1
Plan:
Address: 2075 King Road, Unit 346
Municipality:
Inspection Date: June 24, 2025

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

KITCHEN

-	REPLACE BOTTOM RIGHT CABINET LEFT OF SINK. 2) SECURE ALL KICK PLATES THROUGHOUT CHIPPED.	_____	_____
	REPLACE FRIDGE NOT WORKING	_____	_____
	CHIP AT BOTTOM GABLE BELOW SINK	_____	_____
	STRIP EDGE AT CORNER LEFT FILLER PEELING AT EDGE/ GABLE SHORT AT CEILING	_____	_____
	REPLACE LEFT STOVE GABLE DAMAGED AT FLOOR LINE 2) ADJUST BANK OF DRAWERS	_____	_____

MAIN BATHROOM

-	INSTALL BATH ACCESSORIES ON CABINET/ ABOVE TOILET.	_____	_____
---	--	-------	-------

Enrollment: 346
Purchaser Name: GIANLUCA FRISOLI
Phone Res: (647) 638-6115
Phone Bus:
Closing Date: July 03, 2025
Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder:
Project: Zancor Homes (King Cort) Ltd.
Lot / Phase: 346 / 1
Plan:
Address: 2075 King Road, Unit 346
Municipality:
Inspection Date: June 24, 2025

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

** Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

GIANLUCA FRISOLI

A handwritten signature in black ink, appearing to be "GF" or similar initials.

Purchaser's Name (print)

Purchaser's Signature

Purchaser's Name (print)

Purchaser's Signature

Gisella Fiore

A handwritten signature in black ink, appearing to be "GF" or similar initials.

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2025/06/24

June 24, 2025