

Enrollment: 348
Purchaser Name: RAY D DASS

Phone Res: (905) 460-5807
Phone Bus:
Closing Date: July 04, 2025
Inspector: Gisella Fiore



Vendor / Builder:
Project: Zancor Homes (King Cort) Ltd.
Lot / Phase: 348 / 1
Plan:
Address: 2075 King Road, Unit 348
Municipality:
Inspection Date: June 26, 2025

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

LIVING ROOM

- INCOMPLETE WIRE SHELVING

KITCHEN

- JOINTS COMING APART AT VALANCE ON ANGLE AND REMOVE FILM
1. CHIP AT TOP UPPER CABINET LEFT OF MICROWAVE 2. UPPER CABINET SHELF RIGHT ABOVE
SINK CHIPPED
UPPER CABINET CORNER BOTTOM SHELVES CHIPPED AND TOP SHELF
CHIP ON BOTTOM FRIDGE BOX
ADJUST PLATE BESIDE FRIDGE. ONE SIDE INSET MORE THAN THE OTHER 2. FRIDGE GABLE
LEFT SIDE DAMAGED BOTTOM

MAIN BATHROOM

- GROUT CRACKING IN TUB

MASTER BEDROOM

- INCOMPLETE WIRE SHELVING

Enrollment: 348
Purchaser Name: RAY D DASS
Phone Res: (905) 460-5807
Phone Bus:
Closing Date: July 04, 2025
Inspector: Gisella Fiore



Page 2 of 2

Vendor / Builder:
Project: Zancor Homes (King Cort) Ltd.
Lot / Phase: 348 / 1
Plan:
Address: 2075 King Road, Unit 348
Municipality:
Inspection Date: June 26, 2025

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

** Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

RAY D DASS

A handwritten signature in black ink, appearing to be "Ray D Dass".

Purchaser's Name (print)

Purchaser's Signature

Purchaser's Name (print)

Purchaser's Signature

Gisella Fiore

A handwritten signature in black ink, appearing to be "Gisella Fiore".

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2025/06/26

June 26, 2025