Enrollment: 413

Purchaser Name: Michael J Squadrilla

Doriana Squadrilla

Phone Res: (416) 918-0389 Phone Bus: (416) 804-1733 Closing Date: July 09, 2025 Inspector: Gisella Fiore

HOMES

Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 413 / 1

Plan:

Address: 2075 King Road, Unit 413

Municiaplity:

Inspection Date: July 07, 2025

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

LIVING ROOM		
-	ADJUST BALCONY DOOR	
	REPLACE SCREEN TORN	
KITCHEN		
-	ADJUST CABINETS ABOVE HOODFAN	
	MISSING SHELVE BOTTOM CORNER CABINET	
	SECURE KICKPLATE / GABLE RIGHT OF STOVE NOT SECURE	
MASTER BEDROOM		
-	ADJUST CLOSET DOOR	
MASTER ENSUITE BATH	I	
-	INSTALL TOLIET PAPER HOLDER ON VANITY AND TOWEL RACKS LEFT OF SHOWER DOOR	
	CLOSER TO SHOWER. MASTER 2)MAIN BATH ON CABINET ABOVE TOILET.	

Enrollment: 413

Purchaser Name: Michael J Squadrilla

Doriana Squadrilla

 Phone Res:
 (416) 918-0389

 Phone Bus:
 (416) 804-1733

 Closing Date:
 July 09, 2025

 Inspector:
 Gisella Fiore

ZANCOR HOMES Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 413 / 1

Plan:

Address: 2075 King Road, Unit 413

Municiaplity:

Inspection Date: July 07, 2025

a Fiore Page 2 of 2

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.						
I have inspected my new home and I agree that the description of the items listed on this form are accurate.						
Michael J Squadrilla		Doriana Squadrilla				
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature			
		Gisella Fiore	F/L			
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature			
Date (YYYY/MM/DD)	2025/07/07	July 07, 2025				