

**Enrollment:** 519  
**Purchaser Name:** David A. Science  
  
**Phone Res:** (416) 301-0135  
**Phone Bus:**  
**Closing Date:** July 24, 2025  
**Inspector:** Gisella Fiore



**Vendor / Builder:**  
**Project:** Zancor Homes (King Cort) Ltd.  
**Lot / Phase:** 519 / 1  
**Plan:**  
**Address:** 2075 King Road, Unit 519  
**Municipality:**  
**Inspection Date:** July 17, 2025

Page 1 of 2

Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

**DAMAGED, INCOMPLETE OR MISSING**

- Windows, side lights and other glazing. Window and door screens
- Bathtub sinks and toilets
- Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

**OPERATING CONDITION**

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- Electrical outlets and fixtures
- Gas fireplaces, incl. circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

**KITCHEN**

CABINETS	ADJUST UPPER CABINET ABOVE MICROWAVE, RUBBING 2) CHIPS AT UPPER CABINET ABOVE SINK 3) CHIPS AT UPPER CABINET LEFT OF FRIDGE 4) CHIP AT FRIDGE PANEL 5) KICK PLATES NOT INSTALLED	_____	_____
	1) SECURE WEATHER STRIP IN FREEZER ON LEFT SIDE, LOOSE 2) DISH WASHER NOT TURNING ON	_____	_____

**LIVING ROOM**

WALLS	VENT MISSING IN LIVING AREA	_____	_____
-------	-----------------------------	-------	-------

**LAUNDRY ROOM**

WALLS	REPLACE ACCESS PANEL, ALL SCRATCHED UP	_____	_____
-------	--	-------	-------

**MAIN BATHROOM**

NOTE:	INSTALL BATHROOM ACCESSORIES. TOILET PAPER HOLDER ON CABINET AND TOWEL BAR AT WALL BY TUB	_____	_____
-------	---	-------	-------

**Enrollment:** 519  
**Purchaser Name:** David A. Science  
**Phone Res:** (416) 301-0135  
**Phone Bus:**  
**Closing Date:** July 24, 2025  
**Inspector:** Gisella Fiore



**Vendor / Builder:**  
**Project:** Zancor Homes (King Cort) Ltd.  
**Lot / Phase:** 519 / 1  
**Plan:**  
**Address:** 2075 King Road, Unit 519  
**Municipality:**  
**Inspection Date:** July 17, 2025

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS.

*\* Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.*

I have inspected my new home and I agree that the description of the items listed on this form are accurate.

David A. Science

Purchaser's Name (print)

Purchaser's Signature

A handwritten signature in blue ink, appearing to be "DA Science", written over a horizontal line.

Purchaser's Name (print)

Purchaser's Signature

Gisella Fiore

Designate's Name (print)

Designate's Signature

Inspector's Name (print)

Inspector's Signature

Date (YYYY/MM/DD)

2025/07/17

July 17, 2025