



# MEDI GROUP Service

WO Number : **W-100806**WO Date : **14-Jul-2025**Issued To : **ROYAL EXTERIOR WATERPROOF**Builder : **Zancor****ZAN14**Lot No : **340**Project : **ZANCOR-RIVERS EDGE-WASAG.6-22**Model : **43-8 (D)**Directions : **Wasaga Beach****East side of Sunnidale Road. North of  
Concession 12 Sunnidale Road**

Address :

Contact :

Main Brick : **Kentville**


Main Stone :

Accent Brick :

Accent Stone : **Birchbark Renaissance**

INIT	Item	Work Description	PO	Builder Ref #
✓	1	2. MORTAR RESIDUE SMEARED AROUND LARGE BLOCKS THAT SURROUND THE FRONT DOOR		340JULY1025
				S-076868

*done*

<hr/>		<b>Special Notes :</b>  <b>COMPLETED JUL 21 2025</b>
<b>Homeowner Signature</b>	<b>Date Completed</b>	
<hr/>		
<b>Site Super Signature</b>	<b>Date Completed</b>	




**Zancor Homes (Wasaga River) Ltd.**  
**Warranty Services**  
**Phone: (905) 738-7010**  
**Fax: (905) 738-5948**

**Work Order**

**Closing Date:** 09Jan24  
**Address:** 83 Sun Valley Avenue  
Wasaga, Ontario  
**Location:** Rivers Edge - Phase: 1 - Lot: 340  
**Today's Date:** 26Jun25  
**Contact(s):** Hieu, Thuan Do - Home: (647) 548-8898 - (tonydo04@gmail.com)  
**Email:** tonydo04@gmail.com

**Company:** Medi Group  
**Attention:**  
**Telephone:** (416) 741-2737  
**Fax:** (416) 741-1593

**Please Complete the following items:**

DAI	Type	Issue	Appt. Date/Time	Notes
183524	2 Year	Exterior- General- Around the front door the mortar has shrunk away from the bricks- OVER 2MM WARRANTED 2YEARS	23Jun25 /am	
183525	2 Year	Exterior- General- Around the front door the mortar has shrunk away from the bricks. Also there is mortar residue smeared around the large blocks that surround the front door;- OVER 2MM WARRANTED 2YEARS,	23Jun25 /am	 03/21/25
183526	2 Year	Exterior- General- there is mortar residue smeared around the large blocks that surround the front door- POWER WASH - PROVIDE PHOTO	23Jun25 /am	

183527	2 Year	Exterior- General- there is mortar residue smeared around the large blocks that surround the front door:-POWER WASH- PROVIDE PHOTO		23Jun25 /am	
183528	2 Year	Exterior- General- mortar is off top glass part of front door-		23Jun25 /am	

Date Completed: \_\_\_\_\_

Homeowner Signature: \_\_\_\_\_

The Homeowner acknowledges and accepts all work  
has been completed in a workman like manner.

Date Completed: 07/24/25

Trade &/or Service Tech.

Signature: 

Print Name: \_\_\_\_\_

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, It is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

**Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.**

**Rivers Edge - Phase: 1 - Lot: 340**

**183524 - 1 - 20250623\_142448\_resized - Around the front door the mortar has shrunk away from the bricks- OVER 2MM WARRANTED 2YEARS**



**183525 - 1 - 20250623\_145108\_resized - Around the front door the mortar has shrunk away from the bricks. Also there is mortar residue smeared around the large blocks that surround the front door:- OVER 2MM WARRANTED 2YEARS,**

