



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

THVL
Ave 7/25
8-12 PM.

Closing Date: 26Feb24

Address: 15 Camino Real Drive

Caledon, Ontario L7C 4L8

Location: Caledon Club - Phase: 1B - Lot: Block 196 - Unit 4

Today's Date: 29Jul25

Contact(s): Chetan Harish Kansara - Home: (416) 294-0491 - (Chetankansara71@gmail.com)

Kulwinder Kaur Kooner - Home: (416) 200-9396 - (kinderkooner1@gmail.com)

Email: Chetankansara71@gmail.com

Company: Icon Plumbing & Heating

Attention:

Telephone: (647) 526-0027

Fax:

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
181744	2 Year	Laundry Room- General- When the laundry room sink is running water it stops teh water flow to the shower and washroom upstairs		Done
184854	Interval	Throughout- General- She has at the boiler. Please have the autofill valve looked at by the plumber		Done

Date Completed: Aug 7, 2025

Homeowner Signature: 
The Homeowner acknowledges and accepts all work
has been completed in a workman like manner.

Date Completed: _____

Trade &/or Service Tech.

Signature: _____

Print Name: _____

Please schedule your Service Department to complete work on the above Lot. Should no



Zancor Homes (Caledon) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Aug 7/25
9:30-12PM

Closing Date: 15Jun23

Address: 26 Vincena Road

Caledon, Ontario L7C 4M3

Location: Caledon Club - Phase: 1B - Lot: 38B

Today's Date: 05Aug25

Contact(s): Anshul Jain - Cell: (647) 671-4295 - (seeanshul@gmail.com)

Vishwanath Ramagundam - Cell: (647) 671-4275 - (vishwanathr@hotmail.com)

Email: seeanshul@gmail.com

Company: Icon Plumbing & Heating

Attention:

Telephone: (647) 526-0027

Fax:

Please Complete the following items:

DAI	Type	Issue	Appt. Date/Time	Notes
183985	2 Year	Throughout- General- In all washrooms, the sink water drains very slowly and often gets clogged. This appears to be a systemic issue, potentially related to the overall plumbing or drainage design, and requires further investigation and resolution.- Icon please inspect	05Aug25 /am	Cleared DRAINS, BUILD UP & STOPPER + Cleared KS DRAINS
184977	Emergency	Master Bedroom- General- water leak - water test showed water coming down outside of drainage indicating leak is at tub drain - ICON BOOK ASAP		HANDLED 14015 DAMAGED. TO REVERT

Date Completed: Aug 7/25

Homeowner Signature: 
The Homeowner acknowledges and accepts all work