Enrollment: 308

Purchaser Name: Namir Ahmed Syed

Samreen Amir

Phone Res: (647) 884-9482 Phone Bus: (647) 994-2633 Closing Date: August 15, 2025

Inspector: Alexandria Damianidis

HOMES

Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 308 / 1

Plan:

Address: 2075 King Road, Unit 308

Municiaplity:

Inspection Date: August 11, 2025

Page 1 of 2 Please list below any damaged, incomplete, or missing items and anything that is not in good operating condition. Also note any (substitutions) of items referred to in, or to be selected under, the Agreement of Purchase and Sales (APS). Please initial all changes and deletions. As a minimum, check the following:

DAMAGED, INCOMPLETE OR MISSING

- Windows, side lights and other glazing. Window and door screens
- · Bathtub sinks and toilets
- · Bathroom accessories if provided
- Mirrors, counter tops and cabinetry
- Flooring (hardwood, vinyl, ceramic tiles, carpeting)
- Interior finished and trim carpentry
- Furnace
- Hot water heater, if provided (not rental)
- Exterior finished, driveways, walkways, decks and landscaping

OPERATING CONDITION

- Windows, interior and exterior doors. Door locks
- Faucets: Kitchen, bathroom, laundry room
- Exhaust fans (kitchen, bathrooms) if provided
- · Electrical outlets and fixtures
- Gas fireplaces, incl.circulation fans, if provided
- Heat Recovery Ventilation system, if provided
- · Heating system
- Hot water heater, if provided (not rental)
- Air conditioning system, if provided and if conditions permit

Note		
*	HVAC NOT COMPLETE 2)VENT NOT INSTALLED ABOVE 3)THERMOSTAT NOT TURNING ON	
LIVING ROOM		
WALLS	TV PLUG NOT COMPLETE	
KITCHEN		
CABINETS	CHIP AT UPPER CABINET FACE, LEFT OF FRIDGE 2) ADJUST BOTTOM CABINET BELOW SINK, GAP AND HINGE 3)KICKPLATE MISSING BELOW FREEZER	
MASTER ENSUITE BATH		
SHOWER ENCLOSURE	SHOWER GLASS NOT INSTALLED	
NOTE:	INSTALL BATHROOM ACCESSORIES MARKED WITH GREEN TAPE. TOILET PAPER HOLDER ON CABINET AND TOWEL BAR ON WALL BEHIND ENTRY DOOR MASTER EN	
ELECTRICAL/LIGHTING	ELECTRICAL NOT COMPLETE	
MAIN BATHROOM		
MIRROR	MIRRORS NOT INSTALLED THROUGHOUT	
NOTE:	INSTAL BATH ACCESSORIES, MARKED WITH GREEN TAPE. TOILET PAPER ON CABINET AND TOWEL BAR BESIDE TUB	
LAUNDRY ROOM		
SINK/FAUCET/PLUMBING	APPLIANCES INSTALLED, BUT NOT CONNECTED	
	REPLACE WASHING MACHINE. LARGE DENT ON RIGHT SIDE.	

Enrollment: 308

Purchaser Name: Namir Ahmed Syed

Samreen Amir
Phone Res: (647) 884-9482

Phone Bus: (647) 994-2633
Closing Date: August 15, 2025
Inspector: Alexandria Damianidis

ZANCOR HOMES

Page 2 of 2

Vendor / Builder:

Project: Zancor Homes (King Cort) Ltd.

Lot / Phase: 308 / 1

Plan:

Address: 2075 King Road, Unit 308

Municiaplity:

Inspection Date: August 11, 2025

THE COMPLETED PRE-DELIVERY INSPECTION IS A FORMAL RECORD OF THE HOME'S CONDITION BEFORE THE PURCHASER TAKES POSSESSION IT WILL BE USED AS A REFERENCE FOR FUTURE WARRANTY REQUESTS. * Purchasers or owners who intend to designate someone to conduct the PDI in their place should ensure they provide written authority to the vendor/builder authorizing the designate to sign this form on their behalf.					
I have inspected my new home and I agree that the description of the items listed on this form are accurate.					
	N				
Namir Ahmed Syed		Samreen Amir			
Purchaser's Name (print)	Purchaser's Signature	Purchaser's Name (print)	Purchaser's Signature		
		Alexandria Damianidis	AD		
Designate's Name (print)	Designate's Signature	Inspector's Name (print)	Inspector's Signature		
Date (YYYY/MM/DD)	2025/08/11	August 11, 2025			