1:30 am

ZANCOR Zancor Homes (King Cort) Ltd.
Warranty Services
Phone: (905) 738-7010
Fax: (905) 738-5948

Work Order

Closing Date:
Address:

Location: Today's Date: Contact(s): Email: 15May25
2075 King Road, Unit 246
King City, Ontario
King Terraces - Phase: 1 - Lot: 246
22Jul25
ANDREA MARIE PICCOLI - Cell: (905) 252-5805 - (a.piccoli246@gmail.com) a.piccoli246@gmail.com

KING TERRACE-SERVICE

Company:
Attention:
Telephone:
Fax:

	מנפ נופ וסווס	wing items:			
DAI ·	Туре	ssue		Appt. Date/Time	Notes
184056	30-Day	Foyer- General- Paint		29Jul25	
		coverage on interior-		/am	
		facing side of main door incomplete			
184057	30-Day	Foyer- General Paint		29Jul25	
		coverage incomplete on closet door;		/am	
		baseboards unfinished	1		
		/ messy; door latch unfinished as well as	8		
		hinges			
184058	30-Day	Foyer- General-HVAC		29Jul25	
		rebounding, and		/am	
		construction dust	1		
		(to avoid the drip tray	8		
		getting plugged and overflowing	5		
184060	30-Day	Main Bathroom- General- Panel fo		29Jul25 /am	
		water shut off does not fit. Hole / opening	78		
		appear of the second			

184073	184072	184071	184070	184069	184067	184066	184065	184064	184063	
30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	30-Day	
Bedroom 2- General- Incomplete paint on bedroom wall; correr	Living Room- General- Dry wall / paint coverage incomplete / messy on living com baseboard as well as wall adjacent to terrace doo	Master Bedroom- General- Paint coverage incomplete on pocket door / door frame	Master Bedroom General- Door late unfinished	Kitchen- General- Chips and nicks inside cabinets	Main Bathroom- General- Hole in the ceiling near the exhaust fan. Exhaust fan cover also appears to be bent	Exterior- General- Damage / scratch on railing	Exterior- General- Damage / scratch on railing	Exterior- General- Patio stone on southeast corner of terrace is damaged / cracked	Exterior- General- Patio stone on southeast corner of terrace is damaged / cracked	small in width.
8	8	8	B		*					
29Jul25 /am	29Jul25 /am	29Jul25 /am	29Jul25 /am	29Jul25 /am	29Jul25 ∕/am	29Jul25 /am	29Jul25 /am	29Jul25 /am	29Jul25 /am	
				New Image						

ELECTRICIAN			electrical / switch box appears damaged		
KEDIRERA	29Jul25 /am		Master Bedroom- General- Door on	30-Day	184080
	29Jul25 /am	VX)	Living Room, General- Scratches on window frame	30-Day	184079
	• 11		terrace door as well as beside window adjacent to HVAC		
YEAR EVD	29Jul25 /am		Living Room- General- Unfinished / cracked segment beside	30-Day	184078
	29Jul25 7am	*	Kitchen- General- White gunk / unfinished work between cabinets / countertop	30-Day	184076
	29Jul25 /am	*	Master Ensuite- General- Paint coverage incomplete (ensuite	30-Day	184075
	29Jul25 /am	B	Bedroom 2- General- Dry wall / paint coverage incomplete / messy on walkby door	30-Day	184074
			baseboard unfinished / messy		

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Print Name: Raumen

Signature:

Trade &/or Service Tech

Date Completed: July 29/25

Homeowner Signature: X Ruccol

The Homeowner acknowledges and accepts all work has been completed in a workman like manner.

Date Completed:

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be