



ZANCOR Zancor Homes (King Cort) Ltd. Warranty Services

Phone: (905) 738-7010 Fax: (905) 738-5948

Closing Date:

Address:

Location:

Today's Date:

Contact(s):

11Jul25
2075 King Road, Unit 425
King City, Ontario
King Terraces - Phase: 1 - Lot: 425
08Jul25
Serad Mohamed Hagi Farah Abdi - Cell: (416) 886-1384 - (seradabdi@hotmail.ca)
Faiza Hassan Deria - Cell: (416) 558-8993 - (faizahassan@hotmail.ca)

Faiza Hassan Deria - Cell: (416) 558-8993 - (faizahassan@hotmail.ca)

Faiza Hassan Deria - Cell: (416) 558-8993 - (faizahassan@hotmail.ca)

Faiza Hassan Deria - Cell: (416) 558-8993 - (faizahassan@hotmail.ca)

Faiza Hassan Deria - Cell: (416) 558-8993 - (faizahassan@hotmail.ca)

Email:

seradabdi@hotmail.ca

Company: Attention:

New Image Kitchens

Telephone:

(416) 739-0007

Fax:

(416) 739-7031

Please Complete the following items:

DAI	Туре	Issue		Appt. Date/Time	Notes	
184137	PDI	MASTER ENSUITE BATH~RIGHT GABLE DAMAGED ON BOTTOM	ho	To Net Paper det to RUSTAI	Raplace Apple	Eines Eines
184138	PDI	KITCHEN> GABLE LEFT OF MICROWAVE DAMAGED AND FREEZER PANEL CHIP BOTTOM RIGHT CORNER			Replace / * Kreezes Portol Sysx 715 Euro Coston gr	Drill for high
184139	PDI	KITCHEN~1. KICKPLATE UNDER BANK OF DRAWERS SHORT 2. ALIGN BANK OF DRAWERS 3. DAMAGED UPPER CABINET DOOR ABOVE SINK		Die		10 (NS)
184140	PDI	KITCHEN~FRIDGE GABLE RIGHT SIDE CHIPPED 2. FRIDGE		Ore		

		GABLE LEFT SIDE REMOVE ORANGE STAIN 3. TOP FILLER ABOVE FRIDGE SHORT.		1- Ceiling Stript Longth	Euro Custom
184141	PDI	KITCHEN~MISSING DISHWASHER PANEL (NOT FOUND IN UNIT)	Du		
184144	PDI	MAIN BATHROOM- -~CHIP ON BOTTOM BACK LEFT	pas		
D	<	1 110 5		. 1	_

Date Completed: _	July 9/25	Homeowner Signature: Image: Additional content of the complete of the content of the complete of the content of the conte
Date Completed: _		Trade &/or Service Tech.
		Signature:
		Print Name: 5

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Failure to comply with this request within 10 business days will give Zancor Homes (and it's group of companies) the right to carry out any and all repairs. All costs incurred will be applied to the Company listed above.

Replace (B) Mucro explandor

Euro Busines Antio (M)

322 x 547

OLD DOOR 549

New 546





Zancor Homes (King Cort) Ltd.

Warranty Services Phone: (905) 738-7010

Fax: (905) 738-5948

Work Order

Closing Date: Address:		ng Road, Unit 425				July		
Location: Today's Date: Contact(s):	King Cit King Tei 24Jun25 Serad M Faiza Ha	2075 King Road, Unit 425 King City, Ontario King Terraces - Phase: 1 - Lot: 425 24Jun25 Serad Mohamed Hagi Farah Abdi - Cell: (416) 886-1384 - (seradabdi@hotmail.ca) Faiza Hassan Deria - Cell: (416) 558-8993 - (faizahassan@hotmail.ca) Guled Mohamed Farah Abdi - Cell: (647) 527-8993 - (gmfabdi@gmail.com) seradabdi@hotmail.ca						
Email:	seradabo	seradabdi@hotmail.ca						
Company: Attention: Telephone: Fax:	(416) 739 (416) 739	9-7031				E15 E1L		
Please Compl	Type	Issue		Appt.	Notes	Nous		
	. , , , ,	1.0040		Date/Time		pary		
183752	Quality Control	KITCHEN>INSTALL GABLE RIGHT SIDE OF MICROWAVE			Dore ENS	45 HR \		
183753	Quality Control	MASTER ENSUITE BATH~SECURE KICK PLATE AT BANK OF DRAWERS		28	Held 48 cm	Aplico/ grey E2		
Date Completed:			Homeowner Signature: The Homeowner acknowledges and accepts all work has been completed in a workman like manner.					
Date Completed:			Trade &/or Service Tech.					
			Signatu	ure:				

Please schedule your Service Department to complete work on the above Lot. Should no appointment time or date appear (below) on this form, it is your responsibility to arrange and adhere to the appointment you have scheduled. Your service representative must have this form signed by homeowner on completion. Please fax the signed form to our office (905) 833-4367.

Print Name:

Box so their a Noticeable gap